

Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	Keith Neary	Signature:	
Site Address:	KILCARN WOOD 2 , Kilcarn, Navan, Co. Meath, C15D2E7 , Ireland	Location / Description of Scaffold:	Kilcarn woods 54 to 59
Date & Time of Inspection:	2025-05-30 10:42:57		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Good	No
Sole Boards	Good	No
Base plates & Base Jacks	Good	No
Standards	Good	No
Ledgers	Good	No
Transoms	Good	No
Tie Spacing & Capacity	Good	No
Anchorage test results	Good	No
Facade bracing	Good	No
Pian bracing	Good	No
Cross bracing	Good	No
Guard rails	Good	No
Toe Boards	Good	No
Decking / scaffold boards	Good	No
Scaffolding signs and tags	Good	No
Loading in line with design / Manufacturer's instructions	Yes	No
Access / egress	Good	No
User behaviour / housekeeping	Good	No

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Unauthorised alterations	No	N/a
Anticipated hazards (next 7 days)	No	No
Other (traffic, public, electricity)	No	No

Other outcomes of inspection / Observation: No