

Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	David Kiely - BSS Scaffolding	Signature:	
Site Address:	KILCARN WOOD 2 , Kilcarn, Navan, Co. Meath, C15D2E7 , Ireland	Location / Description of Scaffold:	54-59 kilcarn
Date & Time of Inspection:	2025-06-20 14:05:39		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Good	Na
Sole Boards	Good	Na
Base plates & Base Jacks	Good	Na
Standards	Good	Na
Ledgers	Good	Na
Transoms	Good	Na
Tie Spacing & Capacity	None	Na
Anchorage test results	None	Na
Facade bracing	None	Na
Pian bracing	Good	Na
Cross bracing	None	Na
Guard rails	Good	Na
Toe Boards	Good	Na
Decking / scaffold boards	Good	Na
Scaffolding signs and tags	Good and updated	Na
Loading in line with design / Manufacturer's instructions	All In line with manufacturer's design	Na
Access / egress	Good	Na
User behaviour / housekeeping	Good	Na

Item Inspected	Condition (Include any defected found)	Correctionstaken / required
Unauthorised alterations	None	Na
Anticipated hazards (next 7 days)	None	Na
Other (traffic, public, electriaty)	None	Na

Other outcomes of inspection / Observation: All is good