


Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	David Kiely - BSS Scaffolding	Signature:	
Site Address:	KILCARN WOOD 2 , Kilcarn, Navan, Co. Meath, C15D2E7 , Ireland	Location / Description of Scaffold:	74-76 Kitchen extension single story One lift high
Date & Time of Inspection:	2025-06-29 17:21:35		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Suitable	None
Sole Boards	Good	None
Base plates & Base Jacks	Good	None
Standards	Good	None
Ledgers	Good	None
Transoms	Good	None
Tie Spacing & Capacity	No need for ties	None
Anchorage test results	No anchor test required	None
Facade bracing	None	None
Pian bracing	None	None
Cross bracing	None	None
Guard rails	None	None
Toe Boards	Good	None
Decking / scaffold boards	All boards up to standard	None
Scaffolding signs and tags	No tags	Tags required
Loading in line with design / Manufacturer's instructions	All in line with Manufactures design	None
Access / egress	Access safe and ladder tied Off	None

Item Inspected	Condition (Include any defected found)	Correctionstaken / required
User behaviour / housekeeping	House keeping up to standard	None
Unauthorised alterations	None	None
Anticipated hazards (next 7 days)	None	None
Other (traffic, public, electriaty)	None	Nome

Other outcomes of inspection / Observation: None