

Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	Manado Villano - McElwain	Signature:	
Site Address:	Funchal, Stillorgan Rd, Galloping Green South, Dublin 18, Ireland	Location / Description of Scaffold:	Front building
Date & Time of Inspection:	2025-07-07 13:29:24		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Okay	None
Sole Boards	Okay	None
Base plates & Base Jacks	Okay	None
Standards	Okay	None
Ledgers	Okay	None
Transoms	Okay	None
Tie Spacing & Capacity	Okay	None
Anchorage test results	Okay	None
Facade bracing	Okay	None
Pian bracing	Okay	None
Cross bracing	Okay	None
Guard rails	Okay	None
Toe Boards	Okay	None
Decking / scaffold boards	Okay	None
Scaffolding signs and tags	Okays	None
Loading in line with design / Manufacturer's instructions	N/A	None
Access / egress	Okay	None
User behaviour / housekeeping	Okay	None

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Unauthorised alterations	None	None
Anticipated hazards (next 7 days)	None	None
Other (traffic, public, electricity)	None	None

Other outcomes of inspection / Observation: None