


Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	David Kiely - BSS Scaffolding	Signature:	
Site Address:	Wellfield Avenue, Jamestown, Ráth Tó, Co. Contae na Mí, Ireland	Location / Description of Scaffold:	House 36 3 boxes One lift high Above window roof
Date & Time of Inspection:	2025-08-05 10:25:01		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Good	None
Sole Boards	Good	None
Base plates & Base Jacks	Good	None
Standards	Good	None
Ledgers	Good	None
Transoms	Good	Non e
Tie Spacing & Capacity	None required	None
Anchorage test results	None required	None
Facade bracing	None	None
Pian bracing	None	None
Cross bracing	None	None
Guard rails	None	None
Toe Boards	Alll included	None
Decking / scaffold boards	Good	None
Scaffolding signs and tags	None	Non e
Loading in line with design / Manufacturer's instructions	All in manufacturing design	None
Access / egress	None	None

Item Inspected	Condition (Include any defected found)	Correctionstaken / required
User behaviour / housekeeping	Conditions safe and House keeping good	None
Unauthorised alterations	None	None
Anticipated hazards (next 7 days)	None	None
Other (traffic, public, electriaty)	None	Nome

Other outcomes of inspection / Observation: None