


Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	David Kiely - BSS Scaffolding	Signature:	
Site Address:	Wellfield Avenue, Jamestown, Ráth Tó, Co. Contae na Mí, Ireland	Location / Description of Scaffold:	51-54 wellfield ave 3 lifts high
Date & Time of Inspection:	2025-08-14 10:38:20		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Good	None
Sole Boards	Good	Non e
Base plates & Base Jacks	Good	None
Standards	Good	None
Ledgers	Good	Missing ledgers replaced
Transoms	Good	Missing transoms replaced
Tie Spacing & Capacity	None required	None
Anchorage test results	None required	None
Facade bracing	Good	Bracing added
Pian bracing	None	None
Cross bracing	None	None
Guard rails	None	None
Toe Boards	All toe boards in place	Missing toe boards replaced
Decking / scaffold boards	Some defected boards on scaffolding	Replaced damaged boards
Scaffolding signs and tags	None	None
Loading in line with design / Manufacturer's instructions	All in line with manufacturer's design	None

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Access / egress	Good	None
User behaviour / housekeeping	Good condition	None
Unauthorised alterations	None	None
Anticipated hazards (next 7 days)	None	None
Other (traffic, public, electriaty)	None	None

Other outcomes of inspection / Observation: None