

Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	Eamon Kelly	Signature:	
Site Address:	Bailey HI, Moathill, Navan, Co. Meath, Ireland	Location / Description of Scaffold:	Block B
Date & Time of Inspection:	2025-08-26 08:54:53		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Good	None
Sole Boards	Good	None
Base plates & Base Jacks	Good	None
Standards	Good	None
Ledgers	Good	None
Transoms	Good	None
Tie Spacing & Capacity	N/A	None
Anchorage test results	N/A	None
Facade bracing	Good	None
Pian bracing	Good	None
Cross bracing	Good	None
Guard rails	Missing	Replaced
Toe Boards	Missing	Replaced
Decking / scaffold boards	Good	None
Scaffolding signs and tags	Good	None
Loading in line with design / Manufacturer's instructions	Fair	None
Access / egress	Good	None
User behaviour / housekeeping	Fair	None

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Unauthorised alterations	None that I have seen	None
Anticipated hazards (next 7 days)	None	None
Other (traffic, public, electricity)	None	None

Other outcomes of inspection / Observation: Housekeeping