


Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	MINDAUGAS SMITAS - BSS	Signature:	
Site Address:	KILCARN WOOD 2 , Kilcarn, Navan, Co. Meath, C15D2E7 , Ireland	Location / Description of Scaffold:	73-76 Block back kitchens
Date & Time of Inspection:	2025-09-10 08:56:59		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Good condition	N/A
Sole Boards	Good order	N/A
Base plates & Base Jacks	Good order	N/A
Standards	Good order	N/A
Ledgers	Ledgers missing	N/A
Transoms	Good order	N/A
Tie Spacing & Capacity	None	N/A
Anchorage test results	None	N/A
Facade bracing	None	N/A
Pian bracing	None	N/A
Cross bracing	None	N/A
Guard rails	Good order	N/A
Toe Boards	Missing toe boards	N/A
Decking / scaffold boards	Good order	N/A
Scaffolding signs and tags	None	N/A
Loading in line with design / Manufacturer's instructions	None	N/A
Access / egress	None	N/A
User behaviour / housekeeping	N/A	N/A

Item Inspected	Condition (Include any defects found)	Corrections taken / required
Unauthorised alterations	None	N/A
Anticipated hazards (next 7 days)	None	N/A
Other (traffic, public, electricity)	None	N/A

Other outcomes of inspection / Observation: Observation done scaffold good order