


Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	Eamon Kelly	Signature:	
Site Address:	Castlelea Avenue, Cooltederry, Lansdowne, Co. Laois, R32 YPK3, Ireland	Location / Description of Scaffold:	None 2,3 and 14-17
Date & Time of Inspection:	2025-09-18 09:02:31		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Good	None
Sole Boards	Good	None
Base plates & Base Jacks	Good	None
Standards	Good	None
Ledgers	Good	None
Transoms	Good	None
Tie Spacing & Capacity	Good	None
Anchorage test results	N/A	None
Facade bracing	Good	None
Pian bracing	Good	None
Cross bracing	Good	None
Guard rails	Good	None
Toe Boards	Good	None
Decking / scaffold boards	Good	None
Scaffolding signs and tags	Good	None
Loading in line with design / Manufacturer's instructions	Fair	None
Access / egress	Good	None

Item Inspected	Condition (Include any defected found)	Corrections taken / required
User behaviour / housekeeping	Good	None
Unauthorised alterations	None that I have seen	None
Anticipated hazards (next 7 days)	None	None
Other (traffic, public, electricity)	None	None

Other outcomes of inspection / Observation: None