

# Scaffold GA3

## Report of Results of Inspections of Scaffolds

|                               |                                                                     |                                           |                                                                                     |
|-------------------------------|---------------------------------------------------------------------|-------------------------------------------|-------------------------------------------------------------------------------------|
| Scaffold Owner:               | Kingscroft Development Ltd                                          | Signature:                                |  |
| Scaffold Inspector:           | MINDAUGAS SMITAS - BSS                                              | Signature:                                |  |
| Site Address:                 | KILCARN WOOD 2 ,<br>Kilcarn, Navan, Co.<br>Meath, C15D2E7 , Ireland | Location /<br>Description of<br>Scaffold: | 54-59 Block                                                                         |
| Date & Time of<br>Inspection: | 2025-10-13 15:59:15                                                 |                                           |                                                                                     |

| Item Inspected                                            | Condition (Include any defected found) | Corrections taken / required |
|-----------------------------------------------------------|----------------------------------------|------------------------------|
| Fondations                                                | Good condition                         | N/A                          |
| Sole Boards                                               | Good order                             | N/A                          |
| Base plates & Base Jacks                                  | Good order                             | N/A                          |
| Standards                                                 | Good order                             | N/A                          |
| Ledgers                                                   | Ledger was taken out                   | Ledger put in place          |
| Transoms                                                  | Good order                             | N/A                          |
| Tie Spacing & Capacity                                    | None                                   | N/A                          |
| Anchorage test results                                    | None                                   | N/A                          |
| Facade bracing                                            | None                                   | N/A                          |
| Pian bracing                                              | Good order                             | N/A                          |
| Cross bracing                                             | None                                   | N/A                          |
| Guard rails                                               | Good order                             | N/A                          |
| Toe Boards                                                | Tie board missing                      | N/A                          |
| Decking / scaffold boards                                 | Good order                             | N/A                          |
| Scaffolding signs and tags                                | None                                   | N/A                          |
| Loading in line with design / Manufacturer's instructions | None                                   | N/A                          |
| Access / egress                                           | Good order                             | N/A                          |
| User behaviour / housekeeping                             | Good housekeeping                      | N/A                          |

| Item Inspected                      | Condition (Include any defected found) | Corrections taken / required |
|-------------------------------------|----------------------------------------|------------------------------|
| Unauthorised alterations            | None                                   | N/A                          |
| Anticipated hazards (next 7 days)   | None                                   | N/A                          |
| Other (traffic, public, electriaty) | None                                   | N/A                          |

Other outcomes of inspection / Observation: Scaffold in good order

Images

