

Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	MINDAUGAS SMITAS - BSS	Signature:	
Site Address:	KILCARN WOOD 2 , Kilcarn, Navan, Co. Meath, C15D2E7 , Ireland	Location / Description of Scaffold:	54-59 Block
Date & Time of Inspection:	2025-10-20 16:39:50		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Good condition	N/A
Sole Boards	Good order	N/A
Base plates & Base Jacks	Good order	N/A
Standards	Good order	N/A
Ledgers	Good order	N/A
Transoms	Good order	N/A
Tie Spacing & Capacity	None	N/A
Anchorage test results	None	N/A
Facade bracing	None	N/A
Pian bracing	Good order	N/A
Cross bracing	None	N/A
Guard rails	Good order	N/A
Toe Boards	Good order	N/A
Decking / scaffold boards	Scaffold board rotten	Rotten board replaced
Scaffolding signs and tags	None	N/A
Loading in line with design / Manufacturer's instructions	None	N/A
Access / egress	No access,ladders are out	N/A

Item Inspected	Condition (Include any defected found)	Corrections taken / required
User behaviour / housekeeping	Good order	N/A
Unauthorised alterations	None	N/A
Anticipated hazards (next 7 days)	None	N/A
Other (traffic, public, electriaty)	None	N/A

Other outcomes of inspection / Observation: Scaffold in good order