

# Scaffold GA3

## Report of Results of Inspections of Scaffolds

|                               |                                                                                 |                                           |                                                                                     |
|-------------------------------|---------------------------------------------------------------------------------|-------------------------------------------|-------------------------------------------------------------------------------------|
| Scaffold Owner:               | Kingscroft Development Ltd                                                      | Signature:                                |  |
| Scaffold Inspector:           | Eamon Kelly                                                                     | Signature:                                |  |
| Site Address:                 | Castlelea Avenue,<br>Cooltederry, Lansdowne,<br>Co. Laois, R32 YPK3,<br>Ireland | Location /<br>Description of<br>Scaffold: | No.2+3 , 7-14                                                                       |
| Date & Time of<br>Inspection: | 2025-12-02 10:46:22                                                             |                                           |                                                                                     |

| Item Inspected                                            | Condition (Include any defected found) | Corrections taken / required |
|-----------------------------------------------------------|----------------------------------------|------------------------------|
| Fondations                                                | Good                                   | None                         |
| Sole Boards                                               | Good                                   | None                         |
| Base plates & Base Jacks                                  | Good                                   | None                         |
| Standards                                                 | Good                                   | None                         |
| Ledgers                                                   | Some missing                           | Replaced                     |
| Transoms                                                  | Good                                   | None                         |
| Tie Spacing & Capacity                                    | Good                                   | None                         |
| Anchorage test results                                    | Good                                   | None                         |
| Facade bracing                                            | Good                                   | None                         |
| Pian bracing                                              | Good                                   | None                         |
| Cross bracing                                             | Good                                   | None                         |
| Guard rails                                               | Good                                   | None                         |
| Toe Boards                                                | Good                                   | None                         |
| Decking / scaffold boards                                 | Good                                   | None                         |
| Scaffolding signs and tags                                | Good                                   | None                         |
| Loading in line with design / Manufacturer's instructions | Good                                   | None                         |
| Access / egress                                           | Good                                   | None                         |

| Item Inspected                       | Condition (Include any defects found) | Corrections taken / required |
|--------------------------------------|---------------------------------------|------------------------------|
| User behaviour / housekeeping        | Good                                  | None                         |
| Unauthorised alterations             | Good                                  | None                         |
| Anticipated hazards (next 7 days)    | None                                  | None                         |
| Other (traffic, public, electricity) | None                                  | None                         |

Other outcomes of inspection / Observation: None