

# Scaffold GA3

## Report of Results of Inspections of Scaffolds

|                            |                                                |                                     |                                                                                     |
|----------------------------|------------------------------------------------|-------------------------------------|-------------------------------------------------------------------------------------|
| Scaffold Owner:            | Kingscroft Development Ltd                     | Signature:                          |  |
| Scaffold Inspector:        | Eamon Kelly                                    | Signature:                          |  |
| Site Address:              | Bailey HI, Moathill, Navan, Co. Meath, Ireland | Location / Description of Scaffold: | Block A                                                                             |
| Date & Time of Inspection: | 2025-12-08 13:40:54                            |                                     |                                                                                     |

| Item Inspected                                            | Condition (Include any defected found) | Corrections taken / required |
|-----------------------------------------------------------|----------------------------------------|------------------------------|
| Fondations                                                | Good                                   | None                         |
| Sole Boards                                               | Good                                   | None                         |
| Base plates & Base Jacks                                  | Good                                   | None                         |
| Standards                                                 | Good                                   | None                         |
| Ledgers                                                   | Good                                   | None                         |
| Transoms                                                  | Good                                   | None                         |
| Tie Spacing & Capacity                                    | None                                   | None                         |
| Anchorage test results                                    | None                                   | None                         |
| Facade bracing                                            | None                                   | None                         |
| Pian bracing                                              | None                                   | None                         |
| Cross bracing                                             | Good                                   | None                         |
| Guard rails                                               | Missing                                | Replaced                     |
| Toe Boards                                                | Missing                                | Replaced                     |
| Decking / scaffold boards                                 | Good                                   | None                         |
| Scaffolding signs and tags                                | Good                                   | None                         |
| Loading in line with design / Manufacturer's instructions | Good                                   | None                         |
| Access / egress                                           | Good                                   | None                         |
| User behaviour / housekeeping                             | Good                                   | None                         |

| Item Inspected                       | Condition (Include any<br>defected found) | Corrections taken /<br>required |
|--------------------------------------|-------------------------------------------|---------------------------------|
| Unauthorised alterations             | None                                      | None                            |
| Anticipated hazards (next 7 days)    | None                                      | None                            |
| Other (traffic, public, electricity) | None                                      | None                            |

Other outcomes of inspection / Observation: None