

Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	Dean McDermott	Signature:	
Site Address:	Wellfield Avenue, Jamestown, Ráth Tó, Co. Contae na Mí, Ireland	Location / Description of Scaffold:	Block A 179-182
Date & Time of Inspection:	2026-01-20 09:51:30		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Good	N/a
Sole Boards	Good	N/a
Base plates & Base Jacks	Good	N/a
Standards	Good	N/a
Ledgers	Good	N/a
Transoms	Good	N/a
Tie Spacing & Capacity	Good	N/a
Anchorage test results	N/a	N/a
Facade bracing	Good	N/a
Pian bracing	N/a	N/a
Cross bracing	Good	N/a
Guard rails	N/a	N/a
Toe Boards	Good	N/a
Decking / scaffold boards	Good	N/a
Scaffolding signs and tags	Good	N/a
Loading in line with design / Manufacturer's instructions	Yes	N/a
Access / egress	Good	N/a
User behaviour / housekeeping	Good	N/a

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Unauthorised alterations	N/a	N/a
Anticipated hazards (next 7 days)	N/a	N/a
Other (traffic, public, electricity)	N/a	N/a

Other outcomes of inspection / Observation: All in good working order