


Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	David Kiely - BSS Scaffolding	Signature:	
Site Address:	Wellfield Avenue, Jamestown, Ráth Tó, Co. Contae na Mí, Ireland	Location / Description of Scaffold:	Block 6
Date & Time of Inspection:	2026-04-02 08:40:00		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Good	All in order
Sole Boards	Good	No corrections All in order
Base plates & Base Jacks	Good	No corrections all in order
Standards	Good	No corrections all in order
Ledgers	Ledgers (handrail) bent	Replaced bent handrails
Transoms	Good	All in working conference
Tie Spacing & Capacity	N/a	N/a
Anchorage test results	N/a	N/a
Facade bracing	Good	All in work conditions
Pian bracing	N/a	N/a
Cross bracing	N/a	N/a
Guard rails	Good	All in working condition
Toe Boards	Toes boards missing	Toe boards replaced
Decking / scaffold boards	Bad boards in difficult bays	Boards replaced
Scaffolding signs and tags	All in place	All in order
Loading in line with design / Manufacturer's instructions	Good	All within manufacturing design
Access / egress	Good	All in order

Item Inspected	Condition (Include any defected found)	Corrections taken / required
User behaviour / housekeeping	Good	Area is safe for working
Unauthorised alterations	None	None
Anticipated hazards (next 7 days)	None	None
Other (traffic, public, electriaty)	Good	Good

Other outcomes of inspection / Observation: Everything is good and in working order