

Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	David Kiely - BSS Scaffolding	Signature:	
Site Address:	Wellfield Avenue, Jamestown, Ráth Tó, Co. Contae na Mí, Ireland	Location / Description of Scaffold:	Block 6
Date & Time of Inspection:	2026-04-13 07:35:36		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Good	None taking
Sole Boards	Good	None taking
Base plates & Base Jacks	Good	None taking
Standards	Good	None taking
Ledgers	Good	None taking
Transoms	Good	None taking
Tie Spacing & Capacity	All in good order	None
Anchorage test results	None	None
Facade bracing	Good	None
Pian bracing	Good	None
Cross bracing	Good	None
Guard rails	Good	None
Toe Boards	Good	None
Decking / scaffold boards	Good	None
Scaffolding signs and tags	Good	None
Loading in line with design / Manufacturer's instructions	All in line with manufacturer design	None
Access / egress	Good	None
User behaviour / housekeeping	Area is safe and clean	None

Item Inspected	Condition (Include any defected found)	Correctionstaken / required
Unauthorised alterations	Nome	None
Anticipated hazards (next 7 days)	None	None
Other (traffic, public, electriaty)	None	None

Other outcomes of inspection / Observation: All in order