


# Scaffold GA3

## Report of Results of Inspections of Scaffolds

|                            |                                                   |                                     |                                                                                     |
|----------------------------|---------------------------------------------------|-------------------------------------|-------------------------------------------------------------------------------------|
| Scaffold Owner:            | Kingscroft Development Ltd                        | Signature:                          |  |
| Scaffold Inspector:        | John Moore                                        | Signature:                          |  |
| Site Address:              | Coill Clocha, Oranhill, Galway, H91 F9WH, Ireland | Location / Description of Scaffold: | Scaffold at boundary wall beside house number 198                                   |
| Date & Time of Inspection: | 2026-05-05 08:20:48                               |                                     |                                                                                     |

| Item Inspected                                            | Condition (Include any defected found) | Corrections taken / required |
|-----------------------------------------------------------|----------------------------------------|------------------------------|
| Fondations                                                | Good                                   | N/A                          |
| Sole Boards                                               | Good                                   | N/A                          |
| Base plates & Base Jacks                                  | Good                                   | N/A                          |
| Standards                                                 | Good                                   | N/A                          |
| Ledgers                                                   | Good                                   | N/A                          |
| Transoms                                                  | Good                                   | N/A                          |
| Tie Spacing & Capacity                                    | N/A                                    | N/A                          |
| Anchorage test results                                    | N/A                                    | N/A                          |
| Facade bracing                                            | N/A                                    | N/A                          |
| Pian bracing                                              | N/A                                    | N/A                          |
| Cross bracing                                             | N/A                                    | N/A                          |
| Guard rails                                               | Good                                   | N/A                          |
| Toe Boards                                                | Good                                   | N/A                          |
| Decking / scaffold boards                                 | Good                                   | N/A                          |
| Scaffolding signs and tags                                | Good                                   | N/A                          |
| Loading in line with design / Manufacturer's instructions | Good                                   | N/A                          |
| Access / egress                                           | Good                                   | N/A                          |
| User behaviour / housekeeping                             | Good                                   | N/A                          |

| Item Inspected                       | Condition (Include any defected found) | Corrections taken / required |
|--------------------------------------|----------------------------------------|------------------------------|
| Unauthorised alterations             | N/A                                    | N/A                          |
| Anticipated hazards (next 7 days)    | N/A                                    | N/A                          |
| Other (traffic, public, electricity) | N/A                                    | N/A                          |

Other outcomes of inspection / Observation: Good