

Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	David Kiely - BSS Scaffolding	Signature:	
Site Address:	Bailey HI, Moathill, Navan, Co. Meath, Ireland	Location / Description of Scaffold:	Block 1 2 3
Date & Time of Inspection:	2026-05-14 14:58:15		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	Good	None
Sole Boards	Good	None
Base plates & Base Jacks	Good	None
Standards	Good	None
Ledgers	Good	None
Transoms	Good	None
Tie Spacing & Capacity	None	None required
Anchorage test results	None	None rewuiired
Facade bracing	Good	None
Pian bracing	Good	None
Cross bracing	Good	None
Guard rails	Good	Nonr
Toe Boards	Good	None
Decking / scaffold boards	Good	None
Scaffolding signs and tags	All signs and tags in place	None
Loading in line with design / Manufacturer's instructions	All in line with manufacturer design	None
Access / egress	All access tied off and area clean	None

Item Inspected	Condition (Include any defected found)	Correctionstaken / required
User behaviour / housekeeping	House keeping is good	None
Unauthorised alterations	None	None
Anticipated hazards (next 7 days)	None	None
Other (traffic, public, electriaty)	None	None

Other outcomes of inspection / Observation: All is good