

# Scaffold GA3

## Report of Results of Inspections of Scaffolds

|                               |                                                                     |                                           |                                                                                     |
|-------------------------------|---------------------------------------------------------------------|-------------------------------------------|-------------------------------------------------------------------------------------|
| Scaffold Owner:               | Kingscroft Development Ltd                                          | Signature:                                |  |
| Scaffold Inspector:           | David Kiely - BSS Scaffolding                                       | Signature:                                |  |
| Site Address:                 | KILCARN WOOD 2 ,<br>Kilcarn, Navan, Co.<br>Meath, C15D2E7 , Ireland | Location /<br>Description of<br>Scaffold: | 85-86                                                                               |
| Date & Time of<br>Inspection: | 2026-05-22 07:54:32                                                 |                                           |                                                                                     |

| Item Inspected                                            | Condition (Include any defected found) | Corrections taken / required |
|-----------------------------------------------------------|----------------------------------------|------------------------------|
| Fondations                                                | Good                                   | None                         |
| Sole Boards                                               | Good                                   | None                         |
| Base plates & Base Jacks                                  | Good                                   | None                         |
| Standards                                                 | Good                                   | None                         |
| Ledgers                                                   | Good                                   | None                         |
| Transoms                                                  | Good                                   | None                         |
| Tie Spacing & Capacity                                    | None required                          | None                         |
| Anchorage test results                                    | None require                           | None                         |
| Facade bracing                                            | Good                                   | None                         |
| Pian bracing                                              | Good                                   | None                         |
| Cross bracing                                             | Good                                   | None                         |
| Guard rails                                               | Good                                   | None                         |
| Toe Boards                                                | Good                                   | None                         |
| Decking / scaffold boards                                 | Good                                   | None                         |
| Scaffolding signs and tags                                | All in place                           | None                         |
| Loading in line with design / Manufacturer's instructions | All within manufacturing design        | None                         |
| Access / egress                                           | Good                                   | None                         |
| User behaviour / housekeeping                             | Good                                   | None                         |

| Item Inspected                      | Condition (Include any defected found) | Corrections taken / required |
|-------------------------------------|----------------------------------------|------------------------------|
| Unauthorised alterations            | None                                   | None                         |
| Anticipated hazards (next 7 days)   | None                                   | None                         |
| Other (traffic, public, electriaty) | None                                   | None                         |

Other outcomes of inspection / Observation: None