


Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	Aidan Anthony Odwyer	Signature:	
Site Address:	KILCARN WOOD 2 , Kilcarn, Navan, Co. Meath, C15D2E7 , Ireland	Location / Description of Scaffold:	House No 83 -92
Date & Time of Inspection:	2026-06-18 10:17:36		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	All in good condition/No defects found	None needed
Sole Boards	All in good condition/No defects found	None needed
Base plates & Base Jacks	1 base jack bent	Jack replaced
Standards	All in good condition No defects found	None needed
Ledgers	All in good condition/ no defects found	None needed
Transoms	All in good condition/ no defects found	None needed
Tie Spacing & Capacity	None fitted/not required	None needed
Anchorage test results	Not fitted/none needed	None needed
Facade bracing	None	None
Pian bracing	All in good condition no defects found	None needed
Cross bracing	All in good condition/no defects found	None needed
Guard rails	Good condition/none found	None needed
Toe Boards	All in good condition//no defects found	None needed

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Decking / scaffold boards	All in good condition/No defects found	None needed
Scaffolding signs and tags	All in good condition/and in place	None needed
Loading in line with design / Manufacturer's instructions	All in good condition	None needed
Access / egress	All in good condition/ no defects	None needed
User behaviour / housekeeping	Scaffolding in the process of being cleaned	In process
Unauthorised alterations	None	None needed
Anticipated hazards (next 7 days)	None/scaffolder on site	None
Other (traffic, public, electriaty)	None	None

Other outcomes of inspection / Observation: Scaffolder on site