


# Scaffold GA3

## Report of Results of Inspections of Scaffolds

|                               |                                                                       |                                           |                                                                                     |
|-------------------------------|-----------------------------------------------------------------------|-------------------------------------------|-------------------------------------------------------------------------------------|
| Scaffold Owner:               | Kingscroft Development Ltd                                            | Signature:                                |  |
| Scaffold Inspector:           | Dean McDermott                                                        | Signature:                                |  |
| Site Address:                 | Wellfield Avenue,<br>Jamestown, Ráth Tó, Co.<br>Contae na Mí, Ireland | Location /<br>Description of<br>Scaffold: | 188-201                                                                             |
| Date & Time of<br>Inspection: | 2026-06-23 09:03:12                                                   |                                           |                                                                                     |

| Item Inspected                                            | Condition (Include any defected found) | Corrections taken / required |
|-----------------------------------------------------------|----------------------------------------|------------------------------|
| Fondations                                                | Good                                   | N/A                          |
| Sole Boards                                               | Good                                   | N/A                          |
| Base plates & Base Jacks                                  | Good                                   | N/A                          |
| Standards                                                 | Good                                   | N/A                          |
| Ledgers                                                   | Good                                   | N/A                          |
| Transoms                                                  | Good                                   | N/A                          |
| Tie Spacing & Capacity                                    | Good                                   | N/A                          |
| Anchorage test results                                    | N/A                                    | N/A                          |
| Facade bracing                                            | N/A                                    | N/A                          |
| Pian bracing                                              | N/A                                    | N/A                          |
| Cross bracing                                             | Good                                   | N/A                          |
| Guard rails                                               | Good                                   | N/A                          |
| Toe Boards                                                | Good                                   | N/A                          |
| Decking / scaffold boards                                 | Good                                   | N/A                          |
| Scaffolding signs and tags                                | Good                                   | N/A                          |
| Loading in line with design / Manufacturer's instructions | Yes                                    | N/A                          |
| Access / egress                                           | Good                                   | N/A                          |
| User behaviour / housekeeping                             | Good                                   | N/A                          |

| Item Inspected                       | Condition (Include any defected found) | Corrections taken / required |
|--------------------------------------|----------------------------------------|------------------------------|
| Unauthorised alterations             | None                                   | N/A                          |
| Anticipated hazards (next 7 days)    | N/A                                    | N/A                          |
| Other (traffic, public, electricity) | N/A                                    | N/A                          |

Other outcomes of inspection / Observation: All in good working order