


Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	Aidan Anthony Odwyer	Signature:	
Site Address:	KILCARN WOOD 2 , Kilcarn, Navan, Co. Meath, C15D2E7 , Ireland	Location / Description of Scaffold:	83-92
Date & Time of Inspection:	2026-06-25 13:07:11		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	In good condition/no defects found	No connections needed
Sole Boards	In good condition/no defects found	None needed
Base plates & Base Jacks	All in good condition/no defects found	No connections needed
Standards	All in good condition/ no defects found	No connections needed
Ledgers	All in good condition/no defects found	None needed
Transoms	7 transom / broken and missing pins	Transoms changed..
Tie Spacing & Capacity	None fitted	None needed
Anchorage test results	None fitted	No connections needed
Facade bracing	None fitted	None needed
Pian bracing	In good condition and all in order	None needed
Cross bracing	Fittings rusty	Fittings replaced
Guard rails	None fitted	None needed
Toe Boards	9 toe boards missing	Toe boards replaced
Decking / scaffold boards	13 bad boards found	13 boards replaced
Scaffolding signs and tags	No tags fitted/signage present	None needed

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Loading in line with design / Manufacturer's instructions	In good order	None needed
Access / egress	3 ladders missing..	No replaced/scaffolder working in area
User behaviour / housekeeping	Housekeeping in progress	In progress
Unauthorised alterations	Scaffolder working	None
Anticipated hazards (next 7 days)	Will be doing a further check on friday 26/6/26	Work in progress
Other (traffic, public, electriaty)	All good	None needed

Other outcomes of inspection / Observation: Will be starting a general clean up of scaffolding on friday26 to 29/6