

Scaffold GA3

Report of Results of Inspections of Scaffolds

Scaffold Owner:	Kingscroft Development Ltd	Signature:	
Scaffold Inspector:	Aidan Anthony Odwyer	Signature:	
Site Address:	KILCARN WOOD 2 , Kilcarn, Navan, Co. Meath, C15D2E7 , Ireland	Location / Description of Scaffold:	87 and 88
Date & Time of Inspection:	2026-07-09 11:41:33		

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Fondations	In good condition/no defects found	None needed
Sole Boards	All in good condition/no defects found	None needed
Base plates & Base Jacks	All in good condition/no defects found	None needed
Standards	All in good condition/no defects found	None needed
Ledgers	All in good condition/no defects found	None needed
Transoms	All in good condition/no defects found	None needed
Tie Spacing & Capacity	None fitted /not needed	No connections needed
Anchorage test results	Not needed	Not needed
Facade bracing	None fitted/	None needed
Pian bracing	In good condition/no defects found	No connections needed
Cross bracing	None fitted/	No connections needed
Guard rails	All in good condition/ no defects found	None needed
Toe Boards	Two toe boards missing/rest in good condition	Scaffolder to replace missing toe boards
Decking / scaffold boards	5 boards to be removed and replaced../ not in satisfactory condition	Scaffolder to replace 5 boards

Item Inspected	Condition (Include any defected found)	Corrections taken / required
Scaffolding signs and tags	Loading bay signs in place/no defects found	None needed
Loading in line with design / Manufacturer's instructions	Not applicable	None needed
Access / egress	Ladders in place and correctly tied..	None needed
User behaviour / housekeeping	Blocks insulation and rubble on work platforms. /	In need of cleaning/trip hazard
Unauthorised alterations	None observed at this time	None needed
Anticipated hazards (next 7 days)	General clean up of rubbish/rubble	Work in progress
Other (traffic, public, electriaty)	All in good order	None needed

Other outcomes of inspection / Observation: General clean up needed before next inspection