

GA3 - Report of Results of Inspections of: Work Equipment for Work at a Height

Name of person (or company) for whom the inspection was carried out:

Kingscroft Development Ltd

Address where inspection was carried out (site or other workplace):

Funchal, Stillorgan Rd, Galloping Green South, Dublin 18, Ireland
(Foxrock)

Location & Description of Equipment & any Identification Numbers / Marks	Date and Time of Inspection	Results of Inspection* including defects & locations	Details of any corrective actions taken	Details of any further action necessary	Name and position of person making inspection	Signature of person who made inspection
JOL electrical ladder 01 (A-frame-ladder- 01)	10/12/2025	All good	Na	Na	Gareth Walsh - JOL Electrical	
JOL electrical ladder 02 (A-frame-ladder- 02)	10/12/2025	Good	Na	Na	Gareth Walsh - JOL Electrical	
JOL electrical ladder 03 (A-frame-ladder- 03)	10/12/2025	Good	Na	Na	Gareth Walsh - JOL Electrical	
JOL electrical ladder 04 (A-frame-ladder- 04)	10/12/2025	Good	Na	Na	Gareth Walsh - JOL Electrical	
JOL electrical ladder 05 (A-frame-ladder- 05)	10/12/2025	Good	Na	Na	Gareth Walsh - JOL Electrical	