

GA3 - Report of Results of Inspections of: Work Equipment for Work at a Height

Name of person (or company) for whom the inspection was carried out:

Kingscroft Development Ltd

Address where inspection was carried out (site or other workplace):

Wellfield Avenue, Jamestown, Ráth Tó, Co. Contae na Mí, Ireland
(Ratoath)

Location & Description of Equipment & any Identification Numbers / Marks	Date and Time of Inspection	Results of Inspection* including defects & locations	Details of any corrective actions taken	Details of any further action necessary	Name and position of person making inspection	Signature of person who made inspection
Ross SN:511591125A&B (Block_Grab_single_and_attachment)	05/05/2026	Ok	None	None	Paul Cross	P Cross
Teleporter SN:JCB5A8MGKN3155376 (Ross- JCB-Telerporter)	05/05/2026	Ok	None	None	Paul Cross	P Cross
1 leg Chain sling (CS01Blue)	05/05/2026	Ok	None	Kone	Paul Cross	P Cross
2 leg chain sling (CS02RED)	05/05/2026	Ok	None	None	Paul Cross	P Cross
Jib Extension (581010226)	05/05/2026	Ok	None	Nome	Paul Cross	P Cross