

GA3 - Report of Results of Inspections of: Work Equipment for Work at a Height

* Must specify details of any matters identified that could give rise to a risk to the safety or health of any employee.

Name of person (or company) for whom the inspection was carried out:

DAN McDERMOTT 2055

Address where inspection was carried out (site or other workplace):

GLITCH

Location & Description of Equipment & any Identification Numbers / Marks	Date and Time of Inspection	Results of Inspection * including defects & locations	Details of any corrective actions taken	Details of any further action necessary	Name and position of person making inspection	Signature of person who made inspection
Scaffold Block 171, 172, 173, 174	12-12-25 10:30 AM	In good working order	N/A	N/A	Dan McDermott	[Signature]
Scaffold Block 184, 185, 189, 170	12-12-25 10:45 AM	In good working order	N/A	N/A	Dan McDermott	[Signature]