

* Must specify details of any matters identified that could give rise to a risk to the safety or health of any employee.

GA3 - Report of Results of Inspections of: Work Equipment for Work at a Height

Name of person (or company) for whom the inspection was carried out:

Ross Construction

Address where inspection was carried out (site or other workplace):

Ref: 100

Location & Description of Equipment & any Identification Numbers / Marks	Date and Time of Inspection	Results of Inspection* including defects & locations	Details of any corrective actions taken	Details of any further action necessary	Name and position of person making inspection	Signature of person who made inspection
175-179 Handrails and standards removed	18/3/26 10.00	Handrails removed	Replaced	N/A	Dean M. O'Connell Scaffolder	DMO
183-170 Handrails removed	18/3/26 10.00	Handrails removed	Replaced	N/A	Dean M. O'Connell Scaffolder	DMO
179-182 All good	18/3/26 10.00	All good	-	N/A	Dean M. O'Connell Scaffolder	DMO
171-174 All good	18/3/26 10.00	All good	-	N/A	Dean M. O'Connell Scaffolder	DMO