

RD - MR New Property - Move In Inspection

Red Door Property Management

ksmall@rdpmindy.com




Property	Tenant(s)	Date	Agent / Inspector
1839 Fowler Street		2025-12-17	Paul Jones

Move-Out Conditions

✓ S=Satisfactory

Front Yard/Exterior

Detail	Condition	Actions	Comment
Building Exterior	✓ S	None	
Fence/Gate	✓ S	None	
Landscaping	✓ S	None	
Light Fixture	✓ S	None	
Mailbox/Keyed Location	✓ S	None	
Other	✓ S	None	
Patio Cover	✓ S	None	
Patio/Deck/Balcony	✓ S	None	
Porch/Stairs	✓ S	None	
Sprinkler/Timer	✓ S	None	
Walk/Driveway	✓ S	None	



2025-12-17 12:13:36
[40.1101198, -85.6562795](#)
[View Video](#)

Side Yard/Exterior

Detail	Condition	Actions	Comment
Building Exterior	✓ S	None	
Fence/Gate	✓ S	None	
Landscaping	✓ S	None	
Light Fixture	✓ S	None	
Other	✓ S	None	
Patio Cover	✓ S	None	
Patio/Deck/Balcony	✓ S	None	
Pool/Heater/Equipment	✓ S	None	
Porch/Stairs	✓ S	None	
Spa/Cover/Equipment	✓ S	None	
Sprinkler/Timer	✓ S	None	
Walkway	✓ S	None	



2025-12-17 12:12:59
[40.1101198, -85.6562795](#)
[View Video](#)

Back Yard/Exterior

Detail	Condition	Actions	Comment
Building Exterior	✓ S	None	
Fence/Gate	✓ S	None	
Landscaping	✓ S	None	
Light Fixture	✓ S	None	
Other	✓ S	None	
Patio Cover	✓ S	None	
Patio/Deck/Balcony	✓ S	None	
Pool/Heater/Equipment	✓ S	None	
Porch/Stairs	✓ S	None	
Spa/Cover/Equipment	✓ S	None	
Sprinkler/Timer	✓ S	None	
Walkway	✓ S	None	



2025-12-17 12:02:30
[40.110126, -85.6561234](#)
[View Video](#)

Entry

Detail	Condition	Actions	Comment
Door/Knob/Lock	✓ S	None	
Flooring/Baseboard	✓ S	None	
Light Fixture/Fan	✓ S	None	
Other	✓ S	None	
Switch/Outlet	✓ S	None	
Wall/Ceiling	✓ S	None	



2025-12-17 12:09:42
[40.1096594, -85.6567583](#)
[View Image](#)



2025-12-17 12:10:04
[40.1096594, -85.6567583](#)
[View Image](#)

Living Room

Detail	Condition	Actions	Comment
Door/Knob/Lock	✓ S	None	
Fireplace Equipment	✓ S	None	
Flooring/Baseboard	✓ S	None	
Light Fixture/Fan	✓ S	None	
Other	✓ S	None	
Switch/Outlet	✓ S	None	
Wall/Ceiling	✓ S	None	
Window Covering	✓ S	None	
Window/Lock/Screen	✓ S	None	



2025-12-17 11:53:24
[40.1101287, -85.6560713](#)
[View Video](#)



2025-12-17 11:53:27
[40.1101287, -85.6560713](#)
[View Image](#)



2025-12-17 11:53:31
[40.1101287, -85.6560713](#)
[View Image](#)



2025-12-17 11:53:35
[40.1101287, -85.6560713](#)
[View Image](#)



2025-12-17 11:53:41
[40.1101287, -85.6560713](#)
[View Image](#)

Kitchen

Detail	Condition	Actions	Comment
Cabinets/Drawers	✓ S	None	
Counter	✓ S	None	
Dishwasher	✓ S	None	
Faucet/Plumbing	✓ S	None	
Flooring/Baseboard	✓ S	None	
Light Fixture	✓ S	None	
Microwave	✓ S	None	

Detail	Condition	Actions	Comment
Other	✓ S	None	
Oven	✓ S	None	
Oven/Microwave	✓ S	None	
Range/Fan/Hood/Filter	✓ S	None	
Refrigerator	✓ S	None	
Sink/Disposal	✓ S	None	
Switch/Outlet	✓ S	None	
Trash Compactor	✓ S	None	
Wall/Ceiling	✓ S	None	
Window Covering	✓ S	None	
Window/Lock/Screen	✓ S	None	



2025-12-17 12:04:59
[40.1100904, -85.6561601](#)
[View Image](#)



2025-12-17 12:05:16
[40.1100904, -85.6561601](#)
[View Image](#)



2025-12-17 12:05:25
[40.1100904, -85.6561601](#)
[View Image](#)



2025-12-17 12:05:32
[40.1101183, -85.6561378](#)
[View Image](#)

Dining Room

Detail	Condition	Actions	Comment
Flooring/Baseboard	✓ S	None	
Light Fixture/Fan	✓ S	None	
Other	✓ S	None	
Smoke/CO Detector	✓ S	None	
Switch/Outlet	✓ S	None	
Wall/Ceiling	✓ S	None	
Window Covering	✓ S	None	
Window/Lock/Screen	✓ S	None	



2025-12-17 11:53:58
40.1101287, -85.6560713
[View Video](#)



2025-12-17 11:54:02
40.1101287, -85.6560713
[View Image](#)



2025-12-17 11:54:05
40.1101287, -85.6560713
[View Image](#)



2025-12-17 11:54:09
40.1101287, -85.6560713
[View Image](#)



2025-12-17 11:54:12
40.1101287, -85.6560713
[View Image](#)

Garage/Parking

Detail	Condition	Actions	Comment
Cabinet/Counter	✓ S	None	
Driveway/Floor	✓ S	None	
Electrical/Exposed Wiring	✓ S	None	
Garage Door	✓ S	None	
Light Fixture	✓ S	None	
Other	✓ S	None	
Other Door/Knob/Lock	✓ S	None	
Other Storage/Shelving	✓ S	None	
Switch/Outlet	✓ S	None	
Window/Lock/Screen	✓ S	None	



2025-12-17 11:55:48
[40.1101189, -85.6561348](#)
[View Video](#)



2025-12-17 11:55:53
[40.1101189, -85.6561348](#)
[View Image](#)



2025-12-17 11:55:59
40.1101189, -85.6561348
[View Image](#)



2025-12-17 11:56:04
40.1101189, -85.6561348
[View Image](#)



2025-12-17 11:56:10
40.1101189, -85.6561348
[View Image](#)

Hallway/Stairs

Detail	Condition	Actions	Comment
Closet/Cabinet	✓ S	None	
Flooring/Baseboard	✓ S	None	
Light Fixture	✓ S	None	
Other	✓ S	None	
Railing/Banister	✓ S	None	
Smoke/CO Detector	✓ S	None	
Switch/Outlet	✓ S	None	

Detail	Condition	Actions	Comment
Wall/Ceiling	✓ S	None	



2025-12-17 12:00:37
[40.1101267, -85.656137](#)
[View Video](#)



2025-12-17 12:00:38
[40.1101267, -85.656137](#)
[View Image](#)

Bedroom: 1st bedroom on left

Detail	Condition	Actions	Comment
Closet/Door/Track/Shelving	✓ S	None	
Door/Knob/Lock	✓ S	None	
Flooring/Baseboard	✓ S	None	
Light Fixture/Fan	✓ S	None	
Other	✓ S	None	
Switch/Outlet	✓ S	None	
Wall/Ceiling	✓ S	None	
Window Covering	✓ S	None	
Window/Lock/Screen	✓ S	None	
Smoke Detector	✓ S	None	



2025-12-17 11:58:06
40.1098151, -85.6564703
[View Video](#)



2025-12-17 11:58:08
40.1098151, -85.6564703
[View Image](#)



2025-12-17 11:58:12
40.1098151, -85.6564703
[View Image](#)



2025-12-17 11:58:16
40.1098151, -85.6564703
[View Image](#)



2025-12-17 11:58:21
40.1098151, -85.6564703
[View Image](#)

Bedroom 2: 2nd bedroom on left

Detail	Condition	Actions	Comment
Closet/Door/Track/Shelving	✓ S	None	
Door/Knob/Lock	✓ S	None	
Flooring/Baseboard	✓ S	None	
Light Fixture/Fan	✓ S	None	
Other	✓ S	None	
Switch/Outlet	✓ S	None	
Wall/Ceiling	✓ S	None	
Window Covering	✓ S	None	
Window/Lock/Screen	✓ S	None	
Smoke Detector	✓ S	None	



2025-12-17 11:58:52
[40.1098151, -85.6564703](#)
[View Video](#)



2025-12-17 11:58:56
[40.1098151, -85.6564703](#)
[View Image](#)



2025-12-17 11:59:00
[40.1098151, -85.6564703](#)
[View Image](#)



2025-12-17 11:59:05
[40.1098151, -85.6564703](#)
[View Image](#)



2025-12-17 11:59:09
[40.1098151, -85.6564703](#)
[View Image](#)

Bedroom 3: Bedroom on right

Detail	Condition	Actions	Comment
Closet/Door/Track/Shelving	✓ S	None	
Door/Knob/Lock	✓ S	None	
Flooring/Baseboard	✓ S	None	
Light Fixture/Fan	✓ S	None	
Other	✓ S	None	
Switch/Outlet	✓ S	None	
Wall/Ceiling	✓ S	None	

Detail	Condition	Actions	Comment
Window Covering	✓ S	None	
Window/Lock/Screen	✓ S	None	
Smoke Detector	✓ S	None	



2025-12-17 11:59:28
[40.1101267, -85.656137](#)
[View Video](#)



2025-12-17 11:59:31
[40.1101267, -85.656137](#)
[View Image](#)



2025-12-17 11:59:34
[40.1101267, -85.656137](#)
[View Image](#)



2025-12-17 11:59:38
[40.1101267, -85.656137](#)
[View Image](#)



2025-12-17 11:59:42
40.1101267, -85.656137
[View Image](#)

Bathroom: Hallway

Detail	Condition	Actions	Comment
Cabinet/Counter/Shelving	✓ S	None	
Door/Knob/Lock	✓ S	None	
Exhaust Fan	✓ S	None	
Flooring/Baseboard	✓ S	None	
Light Fixture	✓ S	None	
Medicine Cabinet/Mirror	✓ S	None	
Other	✓ S	None	
Plumbing/Drain	✓ S	None	
Shower Door/Rail/Curtain	✓ S	None	
Sink/Faucet	✓ S	None	
Switch/Outlet	✓ S	None	
Toilet	✓ S	None	
Toilet Paper Holder	✓ S	None	
Towel Rack	✓ S	None	

Detail	Condition	Actions	Comment
Tub/Shower	✓ S	None	
Wall/Ceiling	✓ S	None	
Window Covering	✓ S	None	
Window/Lock/Screen	✓ S	None	



2025-12-17 12:00:07
[40.1101267, -85.656137](#)
[View Video](#)



2025-12-17 12:00:10
[40.1101267, -85.656137](#)
[View Image](#)



2025-12-17 12:00:13
[40.1101267, -85.656137](#)
[View Image](#)



2025-12-17 12:00:15
[40.1101267, -85.656137](#)
[View Image](#)

Bathroom 2: Near garage

Detail	Condition	Actions	Comment
Cabinet/Counter/Shelving	✓ S	None	

Detail	Condition	Actions	Comment
Door/Knob/Lock	✓ S	None	
Exhaust Fan	✓ S	None	
Flooring/Baseboard	✓ S	None	
Light Fixture	✓ S	None	
Medicine Cabinet/Mirror	✓ S	None	
Other	✓ S	None	
Plumbing/Drain	✓ S	None	
Sink/Faucet	✓ S	None	
Switch/Outlet	✓ S	None	
Toilet	✓ S	None	
Toilet Paper Holder	✓ S	None	
Wall/Ceiling	✓ S	None	
Window Covering	✓ S	None	
Window/Lock/Screen	✓ S	None	



2025-12-17 11:54:55
40.1101189, -85.6561348
[View Image](#)



2025-12-17 11:54:57
40.1101189, -85.6561348
[View Image](#)



2025-12-17 11:55:05
 40.1101189, -85.6561348
[View Image](#)

Other Room: Back foyer connecting garage and dining room

Detail	Condition	Actions	Comment
Door/Knob/Lock	✓ S	None	
Flooring/Baseboard	✓ S	None	
Light Fixture/Fan	✓ S	None	
Other	✓ S	None	
Switch/Outlet	✓ S	None	
Wall/Ceiling	✓ S	None	
Window Covering	✓ S	None	
Window/Lock/Screen	✓ S	None	



2025-12-17 11:54:30
40.1101287, -85.6560713
[View Video](#)



2025-12-17 11:54:32
40.1101287, -85.6560713
[View Image](#)



2025-12-17 11:54:35
40.1101287, -85.6560713
[View Image](#)



2025-12-17 11:54:38
40.1101287, -85.6560713
[View Image](#)



2025-12-17 11:54:41
40.1101287, -85.6560713
[View Image](#)

Storage

Detail	Condition	Actions	Comment
Other	✓ S	None	



2025-12-17 12:02:41
40.110126, -85.6561234
[View Image](#)



2025-12-17 12:02:54
40.110126, -85.6561234
[View Image](#)




2025-12-17 12:03:07
40.110126, -85.6561234
[View Image](#)

Keys/Remotes/Devices

Detail	Condition	Actions	Comment
Keys	✓ S	None	
Other	✓ S	None	
Remotes/Devices	✓ S	None	

Detail	Condition	Actions	Comment
Lockbox - Location and code	✓ S	None	Nco on gas meter and SUN on front door



Keys

2025-12-17 12:12:21
40.1101198, -85.6562795
[View Image](#)




Remotes/Devices

2025-12-17 12:04:13
40.1100904, -85.6561601
[View Image](#)



Lockbox - Location and code

2025-12-17 12:12:35
40.1101198, -85.6562795
[View Image](#)



Lockbox - Location and code

2025-12-17 12:14:14
40.1101198, -85.6562795
[View Image](#)

Systems

Detail	Condition	Actions	Comment
Air Conditioning/Filter	✓ S	None	
Thermostat	✓ S	None	
Breaker Box	✓ S	None	

Detail	Condition	Actions	Comment
Furnace	✓ S	None	
Furnace Service Tag	✓ S	None	
Other	✓ S	None	
Water Heater	✓ S	None	
Water Softener	✓ S	None	
Whole House Fan	✓ S	None	
Sewer Cleanout	✓ S	None	
Sprinkler/Timer	✓ S	None	
Water Meter	✓ S	None	



2025-12-17 11:56:17
40.1101189, -85.6561348
[View Image](#)



2025-12-17 11:56:19
40.1101189, -85.6561348
[View Image](#)



2025-12-17 11:56:21
40.1101189, -85.6561348
[View Image](#)



2025-12-17 11:57:41
40.1098151, -85.6564703
[View Image](#)



2025-12-17 12:03:21
40.110126, -85.6561234
[View Image](#)



2025-12-17 12:03:26
40.110126, -85.6561234
[View Image](#)



2025-12-17 12:12:41
40.1101198, -85.6562795
[View Image](#)

Additional Comments

Final Comments

To dispute any findings of this inspection please notify us within 3 business days.

Agent / Inspector Signature

A handwritten signature in black ink, consisting of several loops and a final vertical stroke with a small hook at the bottom.

2025-12-17