



MML: 01/19/2021
CW2020/Production Maps/SSO Maps/2020/2020_12

SSO Failure Cause

EPA Reportable EPA & DHEC Reportable	3rd Party Collapsed Line Debris	Equipment Force Main Grease Wet Weather	PS Failure Roots Treatment Plant	Broad River Crane Creek Gills Creek Mill Creek	Rocky Branch Saluda River Smith Branch West Columbia	City Hall Metro WWTW
---	---------------------------------------	--	--	---	---	-------------------------



1 in = 2 miles



**SSO Failure Causes
Location Map
Year to Date, 2020
01/01/2020 - 12/31/2020**

Prepared For: CleanWater 2020