


We Are Columbia

MMML: 01/19/2021
CW2020/Production_Maps/SSO_Maps/2020/2020_12

SSO Failure Cause					
	EPA Reportable		3rd Party		Equipment
	EPA & DHEC Reportable		Collapsed Line		Force Main
			Debris		Grease
			Wet Weather		PS Failure
			Roots		Rocky Branch
			Treatment Plant		Crane Creek
			Mill Creek		Gills Creek
			West Columbia		Saluda River
			City Hall		Smith Branch
			Metro WWTW		



1 in = 2 miles

0 0.5 1 2 3 Miles

SSO Failure Causes Location Map

December 2020

12/01/2020 - 12/31/2020

Prepared For: CleanWater 2020