

Buurt Check

Centuriedreef 7, 2235BT Valkenburg

Built 1980 · Residential · 126 m²

EXECUTIVE SUMMARY

Of the 5 risk categories, 3 good, 1 moderate, 1 critical. The top concern is climate stress with 15/100. The neighborhood has good livability with strong physical environment. At the viewing, pay attention to: inspect for signs of water damage and ask about flood history.

Key concern

Climate Stress: 15/100. Critical climate risk (heat: medium, flooding: high) — serious flood or heat concerns

Risk summary



Sources: RIVM (Dutch National Health Institute) 2025-01-01, RIVM (Dutch National Health Institute) 2025, Klimateffectatlas (Dutch Climate Atlas) 2024, 3DBAG + SunCalc 2026, Leefbaarometer (Dutch Livability Index) 2024, CBS, 3DBAG / TU Delft + SunCalc 2026-06-21

Prepared: 7 April 2026

RISK DETAILS

Centuriedreef 7, 2235BT Valkenburg

Noise Moderate

66/100

Moderate noise (57 dB) — near WHO annoyance threshold


Measurements

Metric	Your value	Guideline / scale
Lden	57.0 dB	53.0 dB

Context

Lden = day-evening-night weighted noise level (road traffic)

Noise — comparison



Legend: severity-colored bar = this address, blue-gray = peer group, light blue = national, dashed = benchmark

Comparison bars are on the buurt-check 0–100 score scale (not raw units). Higher = better.

Source

Source: RIVM (Dutch National Health Institute) · 2025-01-01

Air Quality Good

82/100

Good air quality (PM2.5: 8.6, NO2: 13.8 ug/m3) — meets WHO guidelines

Measurements


Metric	Your value	Guideline / scale
PM2.5	8.6 µg/m³	5.0 µg/m³
NO ₂	13.8 µg/m³	10.0 µg/m³

Context

PM2.5 = fine particulate matter, NO₂ = nitrogen dioxide (annual mean)

RISK DETAILS

Centuriedreef 7, 2235BT Valkenburg



Climate Stress

Critical

15/100


Critical climate risk (heat: medium, flooding: high) — serious flood or heat concerns

Measurements

Metric	Your value	Guideline / scale
Heat	Medium	Target: low · scale: low / medium / high
Water nuisance	High	Target: low · scale: low / medium / high

Context

Based on modeled heat-stress and water-nuisance scenarios



RISK DETAILS

Centuriedreef 7, 2235BT Valkenburg

Sunlight Good

100/100

Good sunlight (7.0h winter) — adequate direct sun year-round


Measurements

Metric	Your value	Guideline / scale
Winter	7.0 h/day	TNO mild ≈ 3.8 h/day; strict ≈ 6.0 h/day
Equinox	12.0 h/day	EN 17037: minimum 1.5h, medium 3.0h, high 4.0h
Annual average	12.9 h/day	Scale context: higher = brighter over the year
SVF	100%	Open ≥ 60% ; moderate 30–59%
Solar irradiance	897 kWh/m²/year	Scale context: higher = more roof exposure

Context

Score is based on direct winter sun. Winter/equinox/annual average in h/day; SVF = visible sky factor (%); solar irradiance in kWh/m²/year

Sunlight — comparison



Comparison bars are on the buurt-check 0–100 score scale (not raw units). Higher = better.

Source

Source: SunCalc + 3DBAG


SEASONAL SUNLIGHT HOURS

Winter	7.0h
Equinox	12.0h
Summer	16.5h

SKY VIEW FACTOR (SVF)



FACADE ANALYSIS




North (4.5m) facade receives the most winter sunlight (5.5h/day)

Crime Rate

Good

100/100

Low crime area (12.0/1,000 residents) — well below national average



Rates shown per 1,000 residents. This address: 12.0

Source

Source: CBS (Statistics Netherlands) · 2025

Crime data is municipality-level context, not street-level incidents.

ADDITIONAL PROPERTY CHECKS

PREMIUM

**Asbestos Awareness**

Potential asbestos risk flagged from construction year (1980). Request an asbestos inventory before renovation.

Source: BAG construction year heuristic

**Foundation Risk**

No foundation risk signal detected from available data.

Source: BRO soil data + Klimaateffectatlas subsidence

**Ground Lease (Erfpacht)**

No ground lease signal detected. This property appears to be on freehold land.

Source: Municipal ground lease registry

**VvE (Owners' Association)**

No owners' association applicable. This property is not an apartment right.

Source: BAG dwelling unit count

**Lead Pipe Risk**

No lead pipe signal detected from available building data.

Source: BAG construction year heuristic (pre-1960)

**Soil Contamination — Manual Verification Required**

No automated parcel-level soil contamination data is available. The BRO soil information registry is not reliable for parcel-level extraction. Visit bodemloket.nl for postcode 2235BT to retrieve official contamination history.

Action required: bodemloket.nl (postcode 2235BT, manual lookup)

**Direct sun (clear-sky visibility)**

Estimated direct sunlight: winter 7.0h/day, equinox 12.0h/day, summer 16.5h/day. 100/100. Annual average: 12.9 h/day | Solar irradiance: 897 kWh/m²/year.

Source: SunCalc + 3DBAG

VIEWING QUESTIONS

Centuriedreef 7, 2235BT Valkenburg



Use these questions during the viewing and note the answers immediately.

Questions for your viewing

NOISE

- ☐ With windows open on Centuriedreef in Valkenburg, can you hear traffic in the bedroom (66/100)? Current road-noise signal is 57.0 dB Lden.
- ☐ Visit once during evening rush hour on Centuriedreef in Valkenburg and once after 22:00. Is there a clear difference in noise?
- ☐ Ask which rooms face the busiest side of the street and what glazing is installed.

AIR QUALITY

- ☐ Air quality on Centuriedreef in Valkenburg scores well (82/100). Check that ventilation systems are present and well-maintained.

CLIMATE STRESS

- ☐ Because climate stress is elevated on Centuriedreef in Valkenburg (15/100), ask whether heavy rain has ever caused water ingress in the home or street. Current levels are heat: medium, water: high.
- ☐ Check gutters, downspouts, and crawl space/basement for signs of recurring moisture.
- ☐ Ask what heat mitigation is in place (external shading, ventilation, cooling) during warm summer periods.

SUNLIGHT




- ☐ Sunlight exposure on Centuriedreef in Valkenburg scores well (100/100). Confirm natural light in key rooms during your viewing.

CRIME

- ☐ Crime context scores well (100/100). Confirm street lighting, entry controls, and whether the area still feels safe after dark.

SHADOW ANALYSIS

PREMIUM



Legend: teal outline = target building · shadow = no direct sun · December 21 / March 20 / June 21 at 12:00 local time · Source: 3DBAG / TU Delft + SunCalc


A same-time seasonal comparison shows whether winter sun drops off materially versus spring and summer.

NEIGHBORHOOD CONTEXT

't Joght

Katwijk · Moderately urban

Location map



Aerial: PDOK Luchtfoto (CC BY 4.0)

People / Housing / Access

People

Population density
8,351 per km² · top 25%

Household size
3 · top 25%

Single person
24% · bottom 25%

Housing

Owner occupied
84% · top 25%


Property value
€428,000 · top 25%

Access

Train station
5.2 km · above average

Supermarket
1.0 km · above average

Age distribution



Few elderly — 16% aged 65+ vs 22% nationally
Source: CBS Wijken & Buurten 2024


LIVABILITY

PREMIUM

Livability Score

88/100

Good



Dimensions



Improving since 2024



Available neighborhood and municipality comparisons return the same normalized score, so the comparison is summarized in text instead of a chart.

Source: Leefbaarometer · 2024

METHODOLOGY

All risk scores are normalized to a 0–100 scale where higher is better. Scores are based on WHO Environmental Noise Guidelines (2018), WHO Global Air Quality Guidelines (2021), and Klimaateffectatlas flood/heat stress models. Sunlight analysis uses ray-casting against 3D building geometry from 3DBAG. The winter solstice (worst case) determines the risk classification.

Scoring formulas

Category	Input	Score mapping	Method
Noise	40–90 dB Lden	100 → 0	Linear interpolation
Air Quality	PM2.5 5–25 µg/m³, NO ₂ 10–40 µg/m³	100 → 0	Worst-of
Climate	Heat + water stress	Low 85 / med 50 / high 15	Worst-of
Sunlight	Winter direct sun	uren / 6 × 100	Cap at 100

Data sources

BAG (Kadaster)	Building data	WFS verblijfsobject
3DBAG (TU Delft)	3D geometry	OGC API Features (CityJSON)
RIVM	Noise (Lden roads)	WMS Iden_wegverkeer (dated)
RIVM	Air quality	WMS conc_NO2, conc_PM25 (dated)
Klimaateffectatlas	Climate stress	WMS + WFS
CBS	Neighborhood stats	OGC API Features
CBS	Crime	OData v4 (47018NED)
Leefbaarometer	Livability	WFS 2.0
SunCalc + 3DBAG	Sunlight analysis	Ray-casting

Sunlight Analysis Method

Solar position SunCalc (azimuth from north, altitude from horizon)
 Temporal 30-min intervals, 12 representative days/year (21st each month)
 Spatial 1m roof grid, up to 256 sample points
 Obstructions 3DBAG buildings only; vegetation and infrastructure excluded
 Atmospheric Clear-sky geometric analysis (no cloud/weather adjustment)
 Target plane Roof surface analysis (not window or balcony plane)

Where 'peer baseline' is shown, values are modeled from the address's urbanization category (CBS), not averaged from the municipality's full distribution.

Important limitations

All data is indicative and should not replace professional building inspection. Crime data is per municipality, not per street. Environmental measurements may not reflect micro-local conditions.

Report Details

Report ID: 83d41a8c-b7f7-4250-91b3-df9c5fab07a0 | Generated: 2026-04-07T19:47:48+00:00
 VBO: 0537010000024119 | Pand: 0537100000015463
 Buurt: BU05370801 | Gemeente: Katwijk (0537)
 Coordinates: 52.1817N, 4.4264E (WGS84) / 89289, 466392 (EPSG:28992)
 Geocoding: BAG address point (building centroid)
 Methodology: v2.1 (2026-02-28)

Your viewing notes

Use this space for answers, repair quotes, and documents the agent still needs to share.

Log before you leave: agreed repair quotes, promised documents, and the next follow-up date.