

Buurt Check

Damrak 1, 1012 LG Amsterdam

Built 1920 · Residential · 85 m²

EXECUTIVE SUMMARY

Of the 5 risk categories, 2 good, 2 moderate, 1 poor. The top concern is crime with 28/100. The neighborhood has moderate livability with strong amenities. At the viewing, pay attention to: .

Key concern

Crime: 28/100. Crime rate is above the national average.

Risk summary



Sources: RIVM - Atlas Leefomgeving 2024, RIVM - GCN 2024, Klimaateffectatlas 2023, 3DBAG + SunCalc 2024, Leefbaarometer 2024, CBS, 3DBAG / TU Delft + SunCalc 2026-06-21

Prepared: 2 March 2026

RISK DETAILS

Damrak 1, 1012 LG Amsterdam

Noise Moderate

62/100

Moderate road traffic noise. Verify peak evening traffic.

Measurements


Metric	Your value	Guideline / scale
Lden	58.3 dB	53.0 dB

Context

Lden = day-evening-night weighted noise level (road traffic)

Noise — comparison

This address



0 20 40 60 70 80 90 100

Legend: severity-colored bar = this address, gray = peer, dashed = benchmark

Comparison bars are on the buurt-check 0 – 100 score scale (not raw units). Higher = better.

Source

Source: RIVM - Atlas Leefomgeving · 2024

Air Quality Good

81/100

Air quality is good. PM2.5 and NO2 are within limits.

Measurements

Metric	Your value	Guideline / scale
PM2.5	9.2 µg/m³	5.0 µg/m³
NO ₂	18.5 µg/m³	10.0 µg/m³

Context

PM2.5 = fine particulate matter, NO₂ = nitrogen dioxide (annual mean)

Air Quality — comparison

This address



0 20 40 60 70 80 90 100

Comparison bars are on the buurt-check 0 – 100 score scale (not raw units). Higher = better.

Source

Source: RIVM - GCN · 2024

RISK DETAILS

Damrak 1, 1012 LG Amsterdam

Climate Stress Moderate

50/100

Moderate heat stress. Some flood risk in heavy rain.


Measurements

Metric	Your value	Guideline / scale
Heat	Medium	Target: low · scale: low / medium / high
Water nuisance	Low	Target: low · scale: low / medium / high

Context

Based on modeled heat-stress and water-nuisance scenarios

Climate Stress — comparison



Comparison bars are on the buurt-check 0 – 100 score scale (not raw units). Higher = better.

Source

Source: Klimateffectatlas · 2023 · Modeled climate scenario

RISK DETAILS

Damrak 1, 1012 LG Amsterdam

Sunlight Good

72/100

Good sunlight access from a south-facing facade.


Measurements

Metric	Your value	Guideline / scale
Winter	3.5 h/day	TNO mild ≈ 3.8 h/day; strict ≈ 6.0 h/day
Equinox	5.4 h/day	EN 17037: minimum 1.5h, medium 3.0h, high 4.0h
Annual average	5.7 h/day	Scale context: higher = brighter over the year
SVF	63%	Open ≥ 60% ; moderate 30 – 59%
SVF (anisotropic)	59%	Open ≥ 60% ; moderate 30 – 59%
Solar irradiance	915 kWh/m²/year	Scale context: higher = more roof exposure

Context

Score is based on direct winter sun. Winter/equinox/annual average in h/day; SVF = visible sky factor (%); solar irradiance in kWh/m²/year

Sunlight — comparison




Comparison bars are on the buurt-check 0 – 100 score scale (not raw units). Higher = better.

Source

Source: SunCalc + 3DBAG

SEASONAL SUNLIGHT HOURS



SKY VIEW FACTOR (SVF)



FACADE ANALYSIS

Facade	Winter	Summer
South	4.0h	10.9h
East	2.1h	8.0h

South facade receives the most winter sunlight (4.0h/day)

RISK DETAILS

Damrak 1, 1012 LG Amsterdam




Crime rate is above the national average.

Measurements

Metric	Your value	Guideline / scale
Total rate	142.3 per 1,000	—
Burglary	8.7 per 1,000	—
Violent	12.4 per 1,000	—

Crime rate — comparison



Rates shown per 1,000 residents. This address: 142.3 · Netherlands: 52.1

Source


Source: CBS · 2024

Crime data is municipality-level context, not street-level incidents.

SHADOW ANALYSIS

PREMIUM

Winter solstice · 12:00



Spring equinox · 12:00



Summer solstice · 12:00



Legend: teal outline = target building · shadow = no direct sun · December 21 / March 20 / June 21 at 12:00 local time ·
Source: 3DBAG / TU Delft + SunCalc

NEIGHBORHOOD CONTEXT

Burgwallen-Oude Zijde

Amsterdam · Very urban

Location map

Location map unavailable


PDOK aerial imagery did not load during export. The dossier continues without the 150 m map context.

Map source: PDOK Luchtfoto (CC BY 4.0) · unavailable for this export

People / Housing / Access

People	Housing	Access
Population density 15,234 per km2 · top 25%	Owner occupied 22 · bottom 25%	Train station 1 · bottom 25%
Household size 2 · bottom 25%	Property value 385,000 · top 25%	Supermarket 0 · bottom 25%
Single person 68 · top 25%		

Age distribution



Working-age area — 67% aged 25 – 64 vs 50% nationally

Source: CBS Wijken & Buurten 2024


PREMIUM

LIVABILITY

Livability Score

50/100


Moderate



Dimensions



Improving since 2018



Comparison bars are on the buurt-check 0 –100 score scale (not raw units). Higher = better.
Source: Leefbaarometer · 2024

ADDITIONAL PROPERTY CHECKS

PREMIUM



Asbestos Awareness

Potential asbestos risk flagged from construction year (1920). Request an asbestos inventory before renovation.

Source: BAG construction year heuristic



Foundation Risk

Moderate foundation risk. Grondsoort: clay. Consider a foundation survey.

Source: BRO soil data + Klimaateffectatlas subsidence



Ground Lease (Erfpacht)

Ground lease (erfpacht) detected (op basis van gemeente). Gemeente: Amsterdam. Verify lease terms, canon amount, and expiry date with the notary.

Source: Municipal ground lease registry



VvE (Owners' Association)

This is an apartment right (12 eenheden). Request VvE annual documents: reserve fund, maintenance plan, and minutes from the last meeting.

Source: BAG dwelling unit count



Lead Pipe Risk

Potential lead pipes flagged from construction year (1920). Commission a water test and request pipe records from the water utility.

Source: BAG construction year heuristic (pre-1960)



Soil Contamination — Manual Verification Required

No automated parcel-level soil contamination data is available. The BRO soil information registry is not reliable for parcel-level extraction. Visit bodemloket.nl for postcode 1012LG to retrieve official contamination history.

Action required: bodemloket.nl (postcode 1012LG, manual lookup)



Direct sun (clear-sky visibility)

Estimated direct sunlight: winter 3.5h/day, equinox 5.4h/day, summer 8.2h/day. 72/100. Annual average: 5.7 h/day | SVF (anisotropic): 59% | Solar irradiance: 915 kWh/m²/year.

Source: SunCalc + 3DBAG

VIEWING QUESTIONS

Damrak 1, 1012 LG Amsterdam



Use these questions during the viewing and note the answers immediately.

Questions for your viewing

NOISE

- ☐ Open a window facing the street. How loud is traffic?
- ☐ Visit at multiple times to check noise variation.

FOUNDATION

- ☐ Check walls for cracks near windows and doors.
- ☐ Ask for the most recent foundation inspection report.

CRIME

- ☐ Walk the street after dark and check lighting, sightlines, and access control around the entrance (28/100). Latest rate: 142.3 per 1,000 residents.
- ☐ Ask the seller or agent about recent break-ins, nuisance, and whether residents use extra security measures.

METHODOLOGY

All risk scores are normalized to a 0 – 100 scale where higher is better. Scores are based on WHO Environmental Noise Guidelines (2018), WHO Global Air Quality Guidelines (2021), and Klimaateffectatlas flood/heat stress models. Sunlight analysis uses ray-casting against 3D building geometry from 3DBAG. The winter solstice (worst case) determines the risk classification.

Scoring formulas

Category	Input	Score mapping	Method
Noise	40 – 90 dB Lden	100 → 0	Linear interpolation
Air Quality	PM2.5 5 – 25 µg/m³, NO ₂ 10 – 40 µg/m³	100 → 0	Worst-of
Climate	Heat + water stress	Low 85 / med 50 / high 15	Worst-of
Sunlight	Winter direct sun	uren / 6 × 100	Cap at 100

Data sources

BAG (Kadaster)	Building data	WFS verblijfsobject
3DBAG (TU Delft)	3D geometry	OGC API Features (CityJSON)
RIVM	Noise (Lden roads)	WMS lden_wegverkeer (dated)
RIVM	Air quality	WMS conc_NO2, conc_PM25 (dated)
Klimaateffectatlas	Climate stress	WMS + WFS
CBS	Neighborhood stats	OGC API Features
CBS	Crime	OData v4 (47018NED)
Leefbaarometer	Livability	WFS 2.0
SunCalc + 3DBAG	Sunlight analysis	Ray-casting

Sunlight Analysis Method

Solar position SunCalc (azimuth from north, altitude from horizon)
Temporal 30-min intervals, 12 representative days/year (21st each month)
Spatial 1m roof grid, up to 256 sample points
Obstructions 3DBAG buildings only; vegetation and infrastructure excluded
Atmospheric Clear-sky geometric analysis (no cloud/weather adjustment)
Target plane Roof surface analysis (not window or balcony plane)

Where 'peer baseline' is shown, values are modeled from the address's urbanization category (CBS), not averaged from the municipality's full distribution.

Important limitations

All data is indicative and should not replace professional building inspection. Crime data is per municipality, not per street. Environmental measurements may not reflect micro-local conditions.

Report Details

Report ID: rpt-epic4-0001 | Generated: 2026-03-24T14:34:08+00:00
VBO: 0363010012345678 | Pand: 0363100012345678
Buurt: BU03630000 | Gemeente: Amsterdam (0363)
Geocoding: BAG address point (building centroid)
Methodology: v2.1 (2026-02-28)

Your viewing notes

Use this space for answers, repair quotes, and documents the agent still needs to share.

Log before you leave: agreed repair quotes, promised documents, and the next follow-up date.