

Buurt Check

Torenvalk 27, 2235DK Valkenburg

Built 2006 · Residential · 231 m²


EXECUTIVE SUMMARY

Of the 3 risk categories, 2 good, 1 critical. The top concern is climate stress with 15/100. The neighborhood is livability class 8 (very good) with strong physical environment. At the viewing, pay attention to: inspect for signs of water damage and ask about flood history.

Key concern

Climate Stress: 15/100. Critical climate risk (heat: medium, flooding: high) — serious flood or heat concerns

Risk summary



Sources: RIVM (Dutch National Health Institute) 2025-01-01, RIVM (Dutch National Health Institute) 2025, Klimateffectatlas (Dutch Climate Atlas) 2024, SunCalc + 3DBAG, Leefbaarometer (Dutch Livability Index) 2024
Prepared: 8 May 2026

RISK DETAILS

Torenvalk 27, 2235DK Valkenburg

Noise Good

86/100

Quiet area (47 dB) — meets the WHO road-noise guideline


Measurements

Metric	Your value	Guideline / scale
Lden	47.0 dB	53.0 dB

Context

Lden = day-evening-night weighted noise level (road traffic)

Noise — comparison



Legend: severity-colored bar = this address, blue-gray = peer group, light blue = national, dashed = benchmark

Comparison bars are on the buurt-check 0–100 score scale (not raw units). Higher = better.

Source

Source: RIVM (Dutch National Health Institute) · 2025-01-01

Air Quality Good

82/100

Good relative air quality (PM2.5: 8.6, NO2: 13.8 ug/m3), but above WHO AQG for PM2.5 and NO2

Measurements




Metric	Your value	Guideline / scale
PM2.5	8.6 µg/m³	5.0 µg/m³
NO ₂	13.8 µg/m³	10.0 µg/m³

Context

PM2.5 = fine particulate matter, NO₂ = nitrogen dioxide (annual mean)

RISK DETAILS

Torenvalk 27, 2235DK Valkenburg



RISK DETAILS


Torenvalk 27, 2235DK Valkenburg

Sunlight

N/A

N/A

Sunlight — comparison



Comparison bars are on the buurt-check 0–100 score scale (not raw units). Higher = better.

Source

Source: SunCalc + 3DBAG

ADDITIONAL PROPERTY CHECKS

PREMIUM

**Asbestos Awareness**

No age-based asbestos flag in available building data.

Source: BAG construction year heuristic

**Foundation Risk**

No foundation risk signal detected from available data. Year-only fallback used because parcel soil data was unavailable. This classification is therefore only a first-pass signal from construction year.

Source: BAG construction year fallback

**Ground Lease (Erfpacht)**

No ground-lease signal in the municipal prevalence check. Still confirm the ownership status with the seller or deed.

Source: Municipal ground-lease prevalence list

**VvE (Owners' Association)**

No owners' association applicable. This property is not an apartment right.

Source: BAG dwelling unit count

**Lead Pipe Risk**

No lead pipe signal detected from available building data.

Source: BAG construction year heuristic (pre-1960)

**Soil Contamination — Manual Verification Required**

No automated parcel-level soil contamination data is available. The BRO soil information registry is not reliable for parcel-level extraction. Visit bodemloket.nl for postcode 2235DK to retrieve official contamination history.

Action required: bodemloket.nl (postcode 2235DK, manual lookup)


**Roof direct sun (clear-sky visibility)**

Roof direct sun estimate unavailable for this export.

Source: SunCalc + 3DBAG

VIEWING QUESTIONS

Torenvalk 27, 2235DK Valkenburg



Use these questions during the viewing and note the answers immediately.

Questions for your viewing

NOISE

- ☐ Noise levels on Torenvalk in Valkenburg score well (86/100). Confirm quiet conditions by visiting at different times of day.

AIR QUALITY

- ☐ Air quality on Torenvalk in Valkenburg scores well (82/100). Check that ventilation systems are present and well-maintained.

CLIMATE STRESS

- ☐ Because climate stress is elevated on Torenvalk in Valkenburg (15/100), ask whether heavy rain has ever caused water ingress in the home or street. Current levels are heat: medium, water: high.
- ☐ Check gutters, downspouts, and crawl space/basement for signs of recurring moisture.
- ☐ Ask what heat mitigation is in place (external shading, ventilation, cooling) during warm summer periods.

SHADOW ANALYSIS

PREMIUM

Shadow snapshots were unavailable for this export.

NEIGHBORHOOD CONTEXT

't Joght

Katwijk · Moderately urban

Location map



Aerial: PDOK Luchtfoto (CC BY 4.0)

People / Housing / Access

People

Population density
8,351 per km² · top 25%

Household size
2.6 · top 25%

Single person
24.0% · bottom 25%

Housing

Owner occupied
85.0% · top 25%


Property value
€466,000 · top 25%

Access

Train station
5.2 km · below-average access

Supermarket
1.0 km · below-average access

Age distribution



Few elderly — 16% aged 65+ vs 22% nationally
Source: CBS Wijken & Buurten 2024

LIVABILITY

PREMIUM

Livability Class

Class 8

Very Good

Deviation vs national average: around national average (+0.1)

Dimensions

Physical environment	Class 6 · around national average (+0.1)
Safety	Class 6 · around national average (+0.1)
Social cohesion	Class 5 · around national average (+0.0)
Amenities	Class 5 · around national average (-0.0)
Housing quality	Class 5 · around national average (+0.0)

Trend

Improving since 2024



Comparison

Available neighborhood, district, and municipality comparisons fall in the same livability class, so the comparison is summarized in text.

Source: Leefbaarometer · 2024

METHODOLOGY

All risk scores are normalized to a 0–100 scale where higher is better. Scores are based on WHO Environmental Noise Guidelines (2018), WHO Global Air Quality Guidelines (2021), and Klimaateffectatlas flood/heat stress models. Sunlight analysis uses ray-casting against 3D building geometry from 3DBAG. The winter solstice (worst case) determines the risk classification.

Scoring formulas

Category	Input	Score mapping	Method
Noise	40–90 dB Lden	100 → 0	Linear interpolation
Air Quality	PM2.5 5–25 µg/m³, NO ₂ 10–40 µg/m³	100 → 0	Worst-of
Climate	Heat + water stress	Low 85 / med 50 / high 15	Worst-of
Sunlight	Winter roof direct sun	uren / 6 × 100	Cap at 100

Data sources

BAG (Kadaster)	Building data	WFS verblijfsobject
3DBAG (TU Delft)	3D geometry	OGC API Features (CityJSON)
RIVM	Noise (Lden roads)	WMS Iden_wegverkeer (dated)
RIVM	Air quality	WMS conc_NO2, conc_PM25 (dated)
Klimaateffectatlas	Climate stress	WMS + WFS
CBS	Neighborhood stats	OGC API Features
Leefbaarometer	Livability	WFS 2.0
SunCalc + 3DBAG	Sunlight analysis	Ray-casting

Sunlight Analysis Method

Solar position SunCalc (azimuth from north, altitude from horizon)
 Temporal 30-min intervals, 12 representative days/year (21st each month)
 Spatial 1m roof grid, up to 256 sample points
 Obstructions 3DBAG buildings only; vegetation and infrastructure excluded
 Atmospheric Clear-sky geometric analysis (no cloud/weather adjustment)
 Target plane Roof surface analysis (not window or balcony plane)

Where 'peer baseline' is shown, values are modeled from the address's urbanization category (CBS), not averaged from the municipality's full distribution.

Important limitations

All data is indicative and should not replace professional building inspection. Environmental measurements may not reflect micro-local conditions.

Report Details

Report ID: 1de24096-f6b6-4a02-b2f2-73769a6eb3c9 | Generated: 2026-05-08T12:52:32+00:00
 VBO: 0537010000024503 | Pand: 0537100000015775
 Buurt: BU05370801 | Gemeente: Katwijk (0537)
 Coordinates: 52.1824N, 4.4303E (WGS84) / 89556, 466461 (EPSG:28992)
 Geocoding: BAG address point (building centroid)
 Methodology: v2.1 (2026-02-28)

Your viewing notes

Use this space for answers, repair quotes, and documents the agent still needs to share.

Log before you leave: agreed repair quotes, promised documents, and the next follow-up date.