

Property Risk Dossier

Damrak 1, 1012 LG Amsterdam

- Built: 1920
- Use: Residential
- Floor area: 85 m²

Prepared on 2 March 2026

EXECUTIVE SUMMARY

Insufficient data available for summary.

Risk Scores

Category	Score	Severity	Source
Noise	62/100	Moderate	RIVM - Atlas Leefomgeving
Air quality	81/100	Good	RIVM - GCN
Climate stress	50/100	Moderate	Klimaat-effectatlas
Sunlight	Data gap (see Sunlight Status)	Not completed	SunCalc + 3DBAG

Sunlight Status

Data gap: sunlight missing
Sunlight analysis is unavailable for this export. Re-export after opening the 3D model.

Neighborhood Context

- Neighborhood code: BU03630000
- Municipality: Amsterdam
- Density: 15234

Crime Rate

This address: 142.3 per 1,000
National avg: 52.1 per 1,000
Burglary: 8.7
Violent: 12.4
Score: 28/100 (Poor)
Crime rate is above the national average.
Source: CBS · 2024

Additional Property Checks

▲ Asbestos Awareness

Flagged - built in risk period

Potential asbestos risk flagged from construction year. Request an asbestos inventory before renovation.

Source: BAG construction year heuristic

- Foundation Risk

Attention needed - moderate risk

Moderate foundation risk. Consider a foundation survey.

Source: BRO soil data + Klimaateffectatlas subsidence

- Ground Lease (Erfpacht)

Attention needed - verify lease terms

Ground lease detected. Verify lease terms, canon amount, and expiry date with the notary.

Source: Municipal ground lease registry

- VvE (Owners' Association)

Attention needed - request documents

This is an apartment right. Request VvE annual documents and reserve fund details.

Source: BAG dwelling unit count

▲ Lead Pipe Risk

Flagged - building age raises probability

Potential lead pipes flagged from construction year. Commission a water test and request utility records.

Source: BAG construction year heuristic (pre-1960)

- Soil Contamination

Manual verification required

No automated parcel-level soil contamination data is available. BRO soil registry is not reliable for parcel-level extraction. Visit bodemloket.nl with the full property address.

Source: BRO soil registry + bodemloket.nl

✓ Direct sun (clear-sky visibility)

Estimated direct sunlight score: 72/100.

Source: SunCalc + 3DBAG

Viewing Questions

- Open a window facing the street. How loud is traffic?
- Visit at multiple times to check noise variation.
- Check walls for cracks near windows and doors.
- Ask for the most recent foundation inspection report.

Methodology

How we score risks: indicators are normalized to a 0-100 scale where higher is better.

Provenance

- Report ID: rpt-epic4-0001
- VBO: 0363010012345678
- Pand: 0363100012345678

- Buurt: BU03630000
- Methodology: v2.1 (2026-02-28)