

Property Risk Dossier

Damrak 1, 1012 LG Amsterdam

- Built: 1920
- Use: Residential
- Floor area: 85 m²

Prepared on 2 March 2026

EXECUTIVE SUMMARY

Insufficient data available for summary.

Risk Scores

Category	Score	Severity	Source
Noise	62/100	Moderate	RIVM - Atlas Leefomgeving
Air quality	81/100	Good	RIVM - GCN
Climate stress	50/100	Moderate	Klimaat-effectatlas
Sunlight	Data gap (see Sunlight Status)	Not completed	SunCalc + 3DBAG

Sunlight Status

Data gap: sunlight missing

Sunlight analysis is unavailable for this export. Re-export after opening the 3D model.

Neighborhood Context

Neighborhood data unavailable.

Additional Property Checks

- Asbestos Awareness

Manual verification required

Asbestos status unavailable in export pipeline.

Source: BAG construction year heuristic

- Foundation Risk

Manual verification required.

Foundation risk unavailable in export pipeline.

Source: BRO soil data + Klimaateffectatlas subsidence

- Ground Lease (Erfpacht)

Ground lease status unavailable in export pipeline.

Source: Municipal ground lease registry

- VvE (Owners' Association)

VvE status unavailable in export pipeline.

Source: BAG dwelling unit count

- Lead Pipe Risk

Lead pipe status unavailable in export pipeline.

Source: BAG construction year heuristic (pre-1960)

- Soil Contamination

Manual verification required

No automated parcel-level soil contamination data is available. BRO soil registry is not reliable for parcel-level extraction. Visit bodemloket.nl with the full property address.

Source: BRO soil registry + bodemloket.nl

- Direct sun (clear-sky visibility)

Sunlight analysis was not completed before export. Re-export after viewing the 3D model.

Source: SunCalc + 3DBAG

Viewing Questions

No questions available for this export.

Methodology

How we score risks: indicators are normalized to a 0-100 scale where higher is better.

Provenance

- Report ID: rpt-epic4-0001
- VBO: 0363010012345678
- Pand: 0363100012345678
- Buurt: BU03630000
- Methodology: v2.1 (2026-02-28)