

Property Dossier

Damrak 1, 1012 LG Amsterdam

Built: 1920 | Residential | 85 m²

Prepared: 2 March 2026

Risk Overview

Noise	62/100
Air Quality	81/100
Climate Stress	50/100

Risk Analysis

Noise

62/100

Moderate

Moderate road traffic noise. Verify peak evening traffic.

Source: RIVM - Atlas Leefomgeving (2024)

Air Quality

81/100

Good

Air quality is good. PM2.5 and NO2 are within limits.

Source: RIVM - GCN (2024)

Climate Stress

50/100

Moderate

Moderate heat stress. Some flood risk in heavy rain.

Source: Klimaateffectatlas (2023)

Sunlight

None Source: SunCalc + 3DBAG

Neighborhood Profile

Neighborhood data is currently unavailable.

Methodology

Scoring Methodology

All risk indicators are normalized to a 0–100 scale, where higher scores are better. Severity is determined as follows:

Score	Severity	Meaning
70–100	Good	Minimal risk
40–69	Moderate	Further investigation recommended
20–39	Poor	Significant risk — get this checked
0–19	Critical	Serious risk — professional advice required

Data Sources

Indicator	Source
Noise	RIVM — Atlas Leefomgeving (ALO)
Air quality	RIVM — Grootschalige Concentratiekaarten (GCN)
Climate stress	Klimaat-effectatlas (KNMI/Deltares)
Sunlight	3DBAG + SunCalc (own computation)
Neighborhood stats	CBS (Statistics Netherlands)
Livability	Leefbaarometer (Min. BZK)
Crime	CBS Police statistics
Building facts	BAG (Basisregistratie Adressen en Gebouwen)
Energy label	EP-Online (RVO)

Limitations

- This report is based on publicly available data and is intended as indicative guidance only.
- Noise and air quality data are macro-level modeling and may not reflect exact conditions at the address.
- Climate risk coverage varies by region; some layers are not available nationally.
- Sunlight calculations are based on 3D building models and may differ from reality due to vegetation and future construction.
- Verify all information on-site and consult professionals for purchase decisions.

Report ID rpt-epic4-0001
VBO ID 0363010012345678
Methodology v2.1 (2026-02-28)