

Buurt Check


Damrak 1, 1012 LG Amsterdam

Built 1920 · Residential · 85 m²

EXECUTIVE SUMMARY

Of the 3 risk categories, 1 good, 2 moderate. The top concern is climate stress with 50/100. No urgent concerns identified, but verify all scores on-site during your viewing.

Risk summary



Sources: RIVM - Atlas Leefomgeving 2024, RIVM - GCN 2024, Klimaateffectatlas 2023, SunCalc + 3DBAG

Prepared: 2 March 2026

RISK DETAILS

Damrak 1, 1012 LG Amsterdam

Noise Moderate

62/100

Moderate road traffic noise. Verify peak evening traffic.

Measurements

Metric	Your value	Guideline / scale
Lden	58.3 dB	53.0 dB

Context

Lden = day-evening-night weighted noise level (road traffic)

Source

Source: RIVM - Atlas Leefomgeving · 2024

Air Quality Good

81/100

Air quality is good. PM2.5 and NO2 are within limits.

Measurements

Metric	Your value	Guideline / scale
PM2.5	9.2 µg/m³	5.0 µg/m³
NO ₂	18.5 µg/m³	10.0 µg/m³

Context

PM2.5 = fine particulate matter, NO₂ = nitrogen dioxide (annual mean)

Source

Source: RIVM - GCN · 2024

Climate Stress Moderate

50/100

Moderate heat stress. Some flood risk in heavy rain.

Measurements

Metric	Your value	Guideline / scale
Heat	Medium	Target: low · scale: low / medium / high
Water nuisance	Low	Target: low · scale: low / medium / high

Context

Based on modeled heat-stress and water-nuisance scenarios

Source

Source: Klimaateffectatlas · 2023 · Modeled climate scenario

RISK DETAILS

Damrak 1, 1012 LG Amsterdam

Sunlight	N/A	N/A
---	-----	-----

Source

Source: SunCalc + 3DBAG

SHADOW ANALYSIS

PREMIUM

Shadow snapshots were unavailable for this export.

NEIGHBORHOOD CONTEXT

Location map

Location map unavailable

PDOK aerial imagery did not load during export. The dossier continues without the 150 m map context.

Map source: PDOK Luchtfoto (CC BY 4.0) · unavailable for this export

Neighborhood data unavailable.

LIVABILITY

Livability data unavailable.

ADDITIONAL PROPERTY CHECKS

PREMIUM

**Asbestos Awareness**

Asbestos status unavailable in export pipeline.

Source: BAG construction year heuristic

**Foundation Risk**

Foundation risk unavailable in export pipeline.

Source: BRO soil data + Klimaateffectatlas subsidence

**Ground Lease (Erfpacht)**

Ground lease status unavailable in export pipeline.

Source: Municipal ground lease registry

**VvE (Owners' Association)**

VvE status unavailable in export pipeline.

Source: BAG dwelling unit count

**Lead Pipe Risk**

Lead pipe status unavailable in export pipeline.

Source: BAG construction year heuristic (pre-1960)

**Soil Contamination — Manual Verification Required**

No automated parcel-level soil contamination data is available. The BRO soil information registry is not reliable for parcel-level extraction. Visit bodemloket.nl for postcode 1012LG to retrieve official contamination history.


Action required: bodemloket.nl (postcode 1012LG, manual lookup)**Direct sun (clear-sky visibility)**

Direct sun estimate unavailable for this export.

Source: SunCalc + 3DBAG

VIEWING QUESTIONS

Damrak 1, 1012 LG Amsterdam



Use these questions during the viewing and note the answers immediately.

Viewing questions were unavailable for this export. Use the notes section below for your own checks.

METHODOLOGY

All risk scores are normalized to a 0 – 100 scale where higher is better. Scores are based on WHO Environmental Noise Guidelines (2018), WHO Global Air Quality Guidelines (2021), and Klimaateffectatlas flood/heat stress models. Sunlight analysis uses ray-casting against 3D building geometry from 3DBAG. The winter solstice (worst case) determines the risk classification.

Scoring formulas

Category	Input	Score mapping	Method
Noise	40 – 90 dB Lden	100 → 0	Linear interpolation
Air Quality	PM2.5 5 – 25 µg/m³, NO ₂ 10 – 40 µg/m³	100 → 0	Worst-of
Climate	Heat + water stress	Low 85 / med 50 / high 15	Worst-of
Sunlight	Winter direct sun	uren / 6 × 100	Cap at 100

Data sources

BAG (Kadaster)	Building data	WFS verblijfsobject
3DBAG (TU Delft)	3D geometry	OGC API Features (CityJSON)
RIVM	Noise (Lden roads)	WMS lden_wegverkeer (dated)
RIVM	Air quality	WMS conc_NO2, conc_PM25 (dated)
Klimaateffectatlas	Climate stress	WMS + WFS
CBS	Neighborhood stats	OGC API Features
CBS	Crime	OData v4 (47018NED)
Leefbaarometer	Livability	WFS 2.0
SunCalc + 3DBAG	Sunlight analysis	Ray-casting

Sunlight Analysis Method

Solar position SunCalc (azimuth from north, altitude from horizon)
Temporal 30-min intervals, 12 representative days/year (21st each month)
Spatial 1m roof grid, up to 256 sample points
Obstructions 3DBAG buildings only; vegetation and infrastructure excluded
Atmospheric Clear-sky geometric analysis (no cloud/weather adjustment)
Target plane Roof surface analysis (not window or balcony plane)

Where 'peer baseline' is shown, values are modeled from the address's urbanization category (CBS), not averaged from the municipality's full distribution.

Important limitations

All data is indicative and should not replace professional building inspection. Crime data is per municipality, not per street. Environmental measurements may not reflect micro-local conditions.

Report Details

Report ID: rpt-epic4-0001 | Generated: 2026-04-03T11:30:54+00:00
VBO: 0363010012345678 | Pand: 0363100012345678
Buurt: BU03630000 | Gemeente: Amsterdam (0363)
Geocoding: BAG address point (building centroid)
Methodology: v2.1 (2026-02-28)

Your viewing notes

Use this space for answers, repair quotes, and documents the agent still needs to share.

Log before you leave: agreed repair quotes, promised documents, and the next follow-up date.