

buurt-check

Centuriedreef 2, 2235BS Valkenburg

Built 1980 · Residential · 126 m²

EXECUTIVE SUMMARY

Of the 5 risk categories, 4 good, 1 critical. The top concern is climate stress with 15/100. The neighborhood has good livability with strong physical environment. At the viewing, pay attention to: inspect for signs of water damage and ask about flood history.

Key concern

Climate Stress: 15/100. Critical climate risk (heat: medium, flooding: high) — serious flood or heat concerns

Risk summary



Sources: RIVM (Dutch National Health Institute) 2025-01-01, RIVM (Dutch National Health Institute) 2024, Klimaateffectatlas (Dutch Climate Atlas)
Prepared: 10 March 2026

VIEWING QUESTIONS

Centuriedreef 2, 2235BS Valkenburg



Use these questions during the viewing and note the answers immediately.

Questions for your viewing

NOISE

- ☐ Noise levels on Centuriedreef in Valkenburg score well (76/100). Confirm quiet conditions by visiting at different times of day.

AIR QUALITY

- ☐ Air quality on Centuriedreef in Valkenburg scores well (84/100). Check that ventilation systems are present and well-maintained.

CLIMATE STRESS

- ☐ Because climate stress is elevated on Centuriedreef in Valkenburg (15/100), ask whether heavy rain has ever caused water ingress in the home or street. Current levels are heat: medium, water: high.
- ☐ Check gutters, downspouts, and crawl space/basement for signs of recurring moisture.
- ☐ Ask what heat mitigation is in place (external shading, ventilation, cooling) during warm summer periods.

SUNLIGHT

- ☐ Sunlight exposure on Centuriedreef in Valkenburg scores well (83/100). Confirm natural light in key rooms during your viewing.

RISK DETAILS

Centuriedreef 2, 2235BS Valkenburg



Quiet area (52 dB) — well below WHO noise guidelines


Measurements

Metric	Your value	Guideline
Lden	52.0 dB	53.0 dB

Context

Lden = day-evening-night weighted noise level (road traffic)

Noise — comparison



Legend: colored bar = this address, gray = peer, dashed = benchmark

Comparison bars are on the buurt-check 0 –100 score scale (not raw units). Higher = better.

Source

Source: RIVM (Dutch National Health Institute) · 2025-01-01



Good air quality (PM2.5: 8.1, NO2: 12.7 ug/m3) — meets WHO guidelines


Measurements

Metric	Your value	Guideline
PM2.5	8.1 µg/m³	5.0 µg/m³
NO ₂	12.7 µg/m³	10.0 µg/m³

Context

PM2.5 = fine particulate matter, NO₂ = nitrogen dioxide (annual mean)

Air Quality — comparison



Comparison bars are on the buurt-check 0 –100 score scale (not raw units). Higher = better.

Source

Source: RIVM (Dutch National Health Institute) · 2024

RISK DETAILS

Centuriedreef 2, 2235BS Valkenburg



Critical climate risk (heat: medium, flooding: high) — serious flood or heat concerns


Measurements

Metric	Your value	Guideline
Heat	Medium	—
Water nuisance	High	—

Context

Based on heat stress and water nuisance models

Climate Stress — comparison



Comparison bars are on the buurt-check 0 –100 score scale (not raw units). Higher = better.

Source

Source: Klimaateffectatlas (Dutch Climate Atlas) · 2024 · Current climate conditions

RISK DETAILS

Centuriedreef 2, 2235BS Valkenburg



Good sunlight (5.0h winter) — adequate direct sun year-round


Measurements

Metric	Your value	Guideline
Winter	5.0 h/day	—
Annual average	6.3 h/day	—
SVF	62%	—
SVF (anisotropic)	1%	—
Solar irradiance	985 kWh/m²/year	—

Context

Winter/annual average in h/day; SVF = visible sky factor (%); solar irradiance in kWh/m²/year

Sunlight — comparison



Comparison bars are on the buurt-check 0 –100 score scale (not raw units). Higher = better.


Source

Source: SunCalc + 3DBAG

SEASONAL SUNLIGHT HOURS



SKY VIEW FACTOR (SVF)



FACADE ANALYSIS

Facade	Winter	Summer
South (ground)	5.8h	10.9h
South (upper)	4.7h	9.6h
North (ground)	1.6h	5.2h

South (ground) facade receives the most winter sunlight (5.8h/day)

RISK DETAILS

Centuriedreef 2, 2235BS Valkenburg

Crime Rate Good **100/100**

Low crime area (12.0/1,000 residents) — well below national average

Measurements

Metric	Your value	Guideline
Total rate	12.0 per 1,000	—
Burglary	0.0 per 1,000	—
Violent	0.5 per 1,000	—

Crime rate — comparison



Rates shown per 1,000 residents. This address: 12.0

Source

Source: CBS (Statistics Netherlands) · 2025JJ00


Crime data is municipality-level context, not street-level incidents.

NEIGHBORHOOD CONTEXT

't Joght

Katwijk · Moderately urban

Location map



Aerial: PDOK Luchtfoto (CC BY 4.0)

People / Housing / Access

People

Population density
8,351 per km² · top 25%

Household size
3 · top 25%

Single person
24% · bottom 25%

Housing

Owner occupied
84% · top 25%


Property value
€428,000 · top 25%

Access

Train station
5.2 km · above average

Supermarket
1.0 km · above average


Age distribution




Few elderly — 16% aged 65+ vs 22% nationally
Source: CBS Wijken & Buurten 2024

LIVABILITY


PREMIUM



Dimensions



Comparison



Comparison bars are on the buurt-check 0 –100 score scale (not raw units). Higher = better.

Source: Leefbaarometer · 2024

ADDITIONAL PROPERTY CHECKS

PREMIUM

**Asbestos Awareness**

Potential asbestos risk flagged from construction year (1980). Request an asbestos inventory before renovation.

Source: BAG construction year heuristic

**Foundation Risk**

No foundation risk signal detected from available data.

Source: BRO soil data + Klimaateffectatlas subsidence

**Ground Lease (Erfpacht)**

No ground lease signal detected. This property appears to be on freehold land.

Source: Municipal ground lease registry

**VvE (Owners' Association)**

No owners' association applicable. This property is not an apartment right.

Source: BAG dwelling unit count

**Lead Pipe Risk**

No lead pipe signal detected from available building data.

Source: BAG construction year heuristic (pre-1960)

**Soil Contamination — Manual Verification Required**

No automated parcel-level soil contamination data is available. The BRO soil information registry is not reliable for parcel-level extraction. Visit bodemloket.nl with the property address for official contamination history.

Action required: bodemloket.nl (manual lookup)

**Direct sun (clear-sky visibility)**

Estimated direct sunlight: winter 5.0h/day, equinox 7.5h/day, summer 10.0h/day. 83/100. Annual average: 6.3 h/day | SVF (anisotropic): 1% | Solar irradiance: 985 kWh/m²/year.

Source: SunCalc + 3DBAG

METHODOLOGY

All risk scores are normalized to a 0 – 100 scale where higher is better. Scores are based on WHO Environmental Noise Guidelines (2018), WHO Global Air Quality Guidelines (2021), and Klimaateffectatlas flood/heat stress models. Sunlight analysis uses ray-casting against 3D building geometry from 3DBAG. The winter solstice (worst case) determines the risk classification.

Scoring formulas

Category	Input	Score mapping	Method
Noise	40 – 90 dB Lden	100 → 0	Linear interpolation
Air Quality	PM2.5 5 – 25 µg/m³, NO ₂ 10 – 40 µg/m³	100 → 0	Worst-of
Climate	Heat + water stress	Low 85 / med 50 / high 15	Worst-of
Sunlight	Winter direct sun	uren / 6 × 100	Cap at 100

Data sources

BAG (Kadaster)	Building data	WFS verblijfsobject
3DBAG (TU Delft)	3D geometry	OGC API Features (CityJSON)
RIVM	Noise (Lden roads)	WMS lden_wegverkeer (dated)
RIVM	Air quality	WMS conc_NO2, conc_PM25 (dated)
Klimaateffectatlas	Climate stress	WMS + WFS
CBS	Neighborhood stats	OGC API Features
CBS	Crime	OData v4 (47018NED)
Leefbaarometer	Livability	WFS 2.0
SunCalc + 3DBAG	Sunlight analysis	Ray-casting

Sunlight Analysis Method

Solar position SunCalc (azimuth from north, altitude from horizon)
 Temporal 30-min intervals, 12 representative days/year (21st each month)
 Spatial 1m roof grid, up to 256 sample points
 Obstructions 3DBAG buildings only; vegetation and infrastructure excluded
 Atmospheric Clear-sky geometric analysis (no cloud/weather adjustment)
 Target plane Roof surface analysis (not window or balcony plane)

Where 'peer baseline' is shown, values are modeled from the address's urbanization category (CBS), not averaged from the municipality's full distribution.

Important limitations

All data is indicative and should not replace professional building inspection. Crime data is per municipality, not per street. Environmental measurements may not reflect micro-local conditions.

Report Details

Report ID: 29f59a30-46fc-4033-b717-4b949bc74e10 | Generated: 2026-03-10T20:45:03+00:00
 VBO: 0537010000024108 | Pand: 05371000000015452
 Buurt: BU05370801 | Gemeente: Valkenburg (0537)
 Coordinates: 52.1820N, 4.4265E (WGS84) / 89294, 466423 (EPSG:28992)
 Geocoding: BAG address point (building centroid)
 Methodology: v2.1 (2026-02-28)

Your viewing notes

Use this space for answers, repair quotes, and documents the agent still needs to share.

Log before you leave: agreed repair quotes, promised documents, and the next follow-up date.