

Property Risk Dossier

Damrak 1, 1012 LG Amsterdam

- Built: 1920
- Use: Residential
- Floor area: 85 m²

Prepared on 2 March 2026

EXECUTIVE SUMMARY

Insufficient data available for summary.

Risk Scores

Category	Score	Severity	Source
Noise	62	Moderate	RIVM - Atlas Leefomgeving
Air quality	81	Good	RIVM - GCN
Climate stress	50	Moderate	Klimaat-effectatlas
Sunlight	72	–	SunCalc + 3DBAG

Sunlight Status

Sunlight analysis is unavailable.

Neighborhood Context

- Neighborhood code: BU03630000
- Municipality: Amsterdam
- Density: 15234

Crime Rate

This address: 142.3 per 1,000

National avg: 52.1 per 1,000

Burglary: 8.7

Violent: 12.4

Score: 28/100 (Poor)

Crime rate is above the national average.

Source: CBS · 2024

Additional Property Checks

ADDITIONAL CHECKS

Asbestos Awareness

Potential asbestos risk flagged from construction year. Request an asbestos inventory before renovation.Source: BAG construction year heuristic

Foundation Risk

Moderate foundation risk. Soil type: clay. Consider a foundation survey.Source: BRO soil data + Klimaat-effectatlas subsidence

Ground Lease (Erfpacht)

Ground lease (erfpacht) detected. Verify lease terms, canon amount, and expiry date with the notary.Source: Municipal

VvE (Owners' Association)

VvE (Owners' Association)This is an apartment right. Request VvE annual documents and reserve fund details.Source: BAG dwelling unit count

Lead Pipe Risk

Potential lead pipes flagged from construction year. Commission a water test and request utility records.Source: BAG construction year heuristic (pre-1960)

Soil Contamination — Manual Verification Required

No automated parcel-level soil contamination data is available. BRO soil information registry is not reliable for parcel-level extraction. Visit bodemloket.nl with the property address.

Direct sun (clear-sky visibility)

Estimated direct sunlight score: 72/100.Source: SunCalc + 3DBAG

Shadow Snapshots

No shadow snapshot was supplied for this export.

Viewing Questions

- Open a window facing the street. How loud is traffic?
- Visit at multiple times to check noise variation.
- Check walls for cracks near windows and doors.
- Ask for the most recent foundation inspection report.

Methodology

How we score risks: indicators are normalized to a 0–100 scale where higher is better.

Provenance

- Report ID: rpt-epic4-0001
- VBO: 0363010012345678
- Pand: 0363100012345678
- Buurt: BU03630000
- Methodology: v2.1 (2026-02-28)