


Damrak 1, 1012 LG Amsterdam

Built 1920 · Residential · 85 m²

Municipality: Amsterdam · Buurt: BU03630000 · Report ID: rpt-epic4-0001



Summer solstice reference, June 21 at 12:00 local time. Source: 3DBAG / TU Delft + SunCalc.



Executive Summary

Of the 5 risk categories, 2 good, 2 moderate, 1 poor. The top concern is crime with 28/100. The neighborhood has moderate livability with strong amenities. At the viewing, pay attention to: .

Key concern

Crime: 28/100. Crime rate is above the national average.

Four core checks



Sources: RIVM - Atlas Leefomgeving 2024, RIVM - GCN 2024, Klimaateffectatlas 2023, 3DBAG + SunCalc 2024, Leefbaarometer 2024, 3DBAG / TU Delft + SunCalc 2026-06-21
Prepared: 2 March 2026

HOUSE ANALYSIS

Damrak 1, 1012 LG Amsterdam

Noise

62/100

Moderate road traffic noise. Verify peak evening traffic.

Lden **58.3 dB**

WHO guideline (Lden) **53.0 dB**

Benchmarks: Peer baseline (urbanization) 55/100 · Netherlands 60/100 · WHO target 74/100

RIVM - Atlas Leefomgeving · 2024

Air Quality

81/100

Air quality is good. PM2.5 and NO2 are within limits.

PM2.5 **9.2 µg/m³**

WHO guideline PM2.5 **5.0 µg/m³**

Benchmarks: Peer baseline (urbanization) 72/100 · Netherlands 76/100

RIVM - GCN · 2024

Climate Stress

50/100

Moderate heat stress. Some flood risk in heavy rain.

Heat **Medium**

Water nuisance **Low**

Benchmarks: Peer baseline (urbanization) 58/100 · Climate target 70/100

KlimaatEffectAtlas · 2023 · Modeled climate scenario

Sunlight

72/100

Good sunlight access from a south-facing facade.

Annual average **5.7 h/day**

SVF **63%**

Benchmarks: Peer baseline (urbanization) 64/100 · Daylight target 60/100

SunCalc + 3DBAG

Also Verify

Foundation

Moderate risk; ask extra foundation questions. Soil: clay.

BRO + KlimaatEffectAtlas

Ground lease

Ground lease detected; verify canon and expiry date. Municipality: Amsterdam.

Municipal ground-lease registry

Owners' association

Request owners' association documents: reserve fund, maintenance plan, and minutes. 12 units.

BAG dwelling records

Age-based checks

Possible asbestos and/or lead-pipe exposure based on construction year.

BAG construction-year heuristic

Sources: RIVM, KlimaatEffectAtlas, SunCalc + 3DBAG, BAG, BRO, and municipal registries. Comparison bars are on the buurt-check 0 – 100 score scale. Higher = better.

SHADOW ANALYSIS

PREMIUM



Legend: teal outline = target building · shadow = no direct sun · June 21 (summer solstice) · top-view snapshots at 09:00, 12:00, and 15:00 · Source: 3DBAG / TU Delft + SunCalc

Summer Sunlight

Direct summer sunlight: 8.2 h/day · Annual average: 5.7 h/day · SVF: 63% · SVF (anisotropic): 59% · Solar irradiance: 915 kWh/m²/year
SunCalc + 3DBAG

Livability

Livability 50/100 (Moderate). Strongest dimension: amenities. Compared with Centrum-West, Amsterdam. Improving since 2018
Leefbaarometer 2024

Crime Rate

Crime rate is above the national average. This address: 142.3 per 1,000. Netherlands: 52.1 per 1,000. Burglary: 8.7 per 1,000. Violent: 12.4 per 1,000. Municipality-level context, not street-level incidents. Rates shown per 1,000 residents.
CBS 2024. Rates shown per 1,000 residents.

CBS Snapshot

Burgwallen-Oude Zijde · Population density: 15,234 · Owner occupied: 22% · Working-age area — 67% aged 25 – 64 vs 50% nationally
CBS Wijken & Buurten 2024

Per-block sources: 3DBAG / TU Delft + SunCalc, Leefbaarometer, CBS, and Klimateffectatlas.

VIEWING CHECKLIST

Damrak 1, 1012 LG Amsterdam

Use the English and Dutch wording together during the viewing.

Noise / Geluid

- ☐ Open a window facing the street. How loud is traffic?
Open een raam aan de straatkant. Hoe luid is het verkeer?
- ☐ Visit at multiple times to check noise variation.
Bezoek op meerdere tijdstippen voor geluidsverschillen.

Foundation / Fundering

- ☐ Check walls for cracks near windows and doors.
Controleer muren op scheuren bij ramen en deuren.
- ☐ Ask for the most recent foundation inspection report.
Vraag naar het meest recente funderingsrapport.

Crime / Criminaliteit

- ☐ Walk the street after dark and check lighting, sightlines, and access control around the entrance (28/100). Latest rate: 142.3 per 1,000 residents.
Loop na donker door de straat en controleer verlichting, zichtlijnen en toegangscontrole rond de entree (28/100). Laatste cijfer: 142.3 per 1.000 inwoners.
- ☐ Ask the seller or agent about recent break-ins, nuisance, and whether residents use extra security measures.
Vraag verkoper of makelaar naar recente inbraken, overlast en of bewoners extra beveiligingsmaatregelen gebruiken.

Your viewing notes

Use this space for answers, repair quotes, and documents the agent still needs to share.

Log before you leave: agreed repair quotes, promised documents, and the next follow-up date.