

Damrak 1, 1012 LG Amsterdam

Built 1920 · Residential · 85 m²

Municipality: Amsterdam · Buurt: BU03630000 · Report ID: rpt-epic4-0001

Summer reference image unavailable for this export.

Summer solstice reference, June 21 at 12:00 local time. Source: 3DBAG / TU Delft + SunCalc.


Executive Summary

Of the 3 risk categories, 1 good, 2 moderate. The top concern is climate stress with 50/100. No urgent concerns identified, but verify all scores on-site during your viewing.

Key concern

No immediate red flag in the core scores. Verify noise, daylight, and ventilation during the viewing.

Four core checks



Sources: RIVM - Atlas Leefomgeving 2024, RIVM - GCN 2024, Klimateffectatlas 2023, SunCalc + 3DBAG
Prepared: 2 March 2026

HOUSE ANALYSIS

Damrak 1, 1012 LG Amsterdam

Noise

62/100



Moderate road traffic noise. Verify peak evening traffic.

Lden **58.3 dB**

WHO guideline (Lden) **53.0 dB**

RIVM - Atlas Leefomgeving · 2024

Air Quality

81/100



Air quality is good. PM2.5 and NO2 are within limits.

PM2.5 **9.2 µg/m³**

WHO guideline PM2.5 **5.0 µg/m³**

RIVM - GCN · 2024

Climate Stress

50/100



Moderate heat stress. Some flood risk in heavy rain.


Heat **Medium**

Water nuisance **Low**

Klimaat-effectatlas · 2023 · Modeled climate scenario

Sunlight

N/A



SunCalc + 3DBAG

Also Verify

Foundation

Unavailable in this export.

Ground lease

Unavailable in this export.

Owners' association

Unavailable in this export.

Age-based checks

Unavailable in this export.

Sources: RIVM, Klimaat-effectatlas, SunCalc + 3DBAG, BAG, BRO, and municipal registries.
Comparison bars are on the buurt-check 0 – 100 score scale. Higher = better.

NEIGHBORHOOD EVIDENCE

Summer shadow evidence is unavailable for this export.

Summer Sunlight

Summer sunlight data is unavailable in this export.

SunCalc + 3DBAG

Livability

Livability data unavailable.

Leefbaarometer

Crime Rate

Crime context unavailable.

CBS

CBS Snapshot

CBS neighborhood data unavailable.

CBS Wijken & Buurten

Per-block sources: 3DBAG / TU Delft + SunCalc, Leefbaarometer, CBS, and Klimaateffectatlas.

VIEWING CHECKLIST

Damrak 1, 1012 LG Amsterdam

Use the English and Dutch wording together during the viewing.

No checklist was available. Use the notes section below.

Your viewing notes

Use this space for answers, repair quotes, and documents the agent still needs to share.

Log before you leave: agreed repair quotes, promised documents, and the next follow-up date.