

Estructura JSON diagnóstico

```
{
  "device_id": "SensyWall",
  "status": 1,
  "passive_mA": 36.25,
  "voltage_V": 4.96,
  "components": [
    {
      "comp_id": "matriz_led_1",
      "type": "matriz_LED",
      "err_code": 0,
      "details": {
        "connection": {
          "bus": "i2c",
          "addres": "0x50"
        },
        "calibration": {
          "nominal_mA": 323.75,
          "min_mA": 316.75,
          "max_mA": 330.75
        },
        "measured_mA": 323.75
      }
    },
    {
      "comp_id": "matriz_led_2",
      "type": "matriz_LED",
      "err_code": 0,
      "details": {
        "connection": {
          "bus": "i2c",
          "addres": "0x53"
        },
        "calibration": {
          "nominal_mA": 323.75,
          "min_mA": 316.75,
          "max_mA": 330.75
        },
        "measured_mA": 323.75
      }
    },
    {
      "comp_id": "matriz_led_3",
```

```
    "type": "matriz_LED",
    "err_code": 1,
    "details": {
      "connection": {
        "bus": "i2c",
        "addres": "0x5C"
      },
      "calibration": {
        "nominal_mA": 323.75,
        "min_mA": 316.75,
        "max_mA": 330.75
      },
      "measured_mA": 313.75
    }
  }
]
```