



Preventive Maintenance Report

- Asset Inspection & Maintenance Record -

PM #3

Maintenance & Agency Details

PM Date: 07 July 2026

Recipient:	Seksyen ICT (3)
Department:	Pusat Kecemerlangan Pengurusan Bencana Malaysia
Position:	Seksyen ICT (3)
Contract:	PERKHIDMATAN SEWAAN PERKAKASAN ICT,PENYELENGGARAAN KOMPREHENSIF DAN BANTUAN SOKONGAN BAGI TEMPOH 37 BULAN DI AGENSI PENGURUSAN BENCANA NEGARA (NADMA)

Asset Information

Serial Number:	CD9TW74	Asset Tag ID:	NADMA-T25020	Customer:	NADMA
Item Name:	Tablet	Category:	Laptop	Model:	Dell Latitude 7350 Detachable
Remarks:	-				

Inspection Checklist

No.	Checklist Item	Yes	No	Remarks
1	Check power and cable plugged in correctly and securely	✓		-
2	Check the monitor screen functionality	✓		-
3	Check the keyboard's key functionality	✓		-
4	Check the mouse's left and right button and scroll wheel functionality	✓		-
5	Hard Disk capacity	✓		-
6	Defragmenter & delete *.tmp file	✓		-
7	Check memory usage	✓		-
8	Operating System (Microsoft Windows) activated & updated	✓		-
9	Microsoft Office activated & updated	✓		-
10	Antivirus activated & updated	✓		-
11	Cables unplugged and re-plugged	✓		-
12	Cleaning / removing dust and stains from body parts of asset	✓		-
13	Check & update username, serial number, asset number and asset location	✓		-
14	Update PM date on the sticker	✓		-

Accessories

Charger:

Mouse:

Other Accessories:

Technician Acknowledgment

Name: Nurul Hazirah Binti Idris

Signature:

Date: 07 July 2026

Recipient Acknowledgment

Name: Seksyen ICT (3)

Department: Pusat Kecemerlangan Pengurusan Bencana Malaysia

Signature:

Date: 06 August 2026