



Preventive Maintenance Report

- Asset Inspection & Maintenance Record -

PM #9

Maintenance & Agency Details

PM Date: 24 July 2026

Recipient:	POOL
Department:	Aras 3
Position:	Aras 3
Contract:	test

Asset Information

Serial Number:	12345	Asset Tag ID:	test123	Customer:	test
Item Name:	Komputer Meja All-In-One	Category:	Desktop	Model:	Dell OptiPlex All-in-One Plus 7420
Remarks:	testing				

Inspection Checklist

No.	Checklist Item	Yes	No	Remarks
1	Check power and cable plugged in correctly and securely	✓		-
2	Check the monitor screen functionality		✓	-
3	Check the keyboard's key functionality		✓	-
4	Check the mouse's left and right button and scroll wheel functionality		✓	-
5	Hard Disk capacity		✓	-
6	Defragmenter & delete *.tmp file		✓	-
7	Check memory usage		✓	-
8	Operating System (Microsoft Windows) activated & updated		✓	-
9	Microsoft Office activated & updated		✓	-
10	Antivirus activated & updated		✓	-
11	Cables unplugged and re-plugged		✓	-
12	Cleaning / removing dust and stains from body parts of asset		✓	-
13	Check & update username, serial number, asset number and asset location		✓	-
14	Update PM date on the sticker		✓	-

Accessories

: 234235322

Other Accessories:

Technician Acknowledgment

Name: seed user
Signature: _____
Date: 24 July 2026

Recipient Acknowledgment

Name: POOL
Department: Aras 3
Signature: 
Date: 24 July 2026