

		COMPANY	JOB	UNIT
		TOTAL E&P Mocambique Area 1 Limitada	032235	00
		Project	QC CODE	
Mozambique LNG		PAI 0101 03M		
		REPORT N°		
		PAI010103M-YAN-00002 A		



COMPANY
TOTAL E&P Mocambique Area 1 Limitada

Project
Mozambique LNG

JOB
032235

UNIT
00

QC CODE
PAI 0101 03M

REPORT N°
PAI010103M-YAN-00002 A

DFT CHECK

Alignment sheet/Drawing number:N/A

Specifications:
MZ-000-CCX-MC-SPC-00001
MZ-000-CCX-CO-PRO-39092-YAN-Painting Procedure

[illegible]

NOTES: C=conforming; NC=no conforming. P=Primer, I (layer)=Intermediate (1, 2, 3, etc.)
F=Final

NOI NO.
MOZ-LNG-YAN-QC-NOI-00240

SUBCONTRACTOR		JOTUN TS		COMPANY	
NAME	Liu Chengyang	NAME	Dai Xiaoliang	NAME	
SIGNATURE		SIGNATURE		SIGNATURE	
DATE	02-Jan-26	DATE	26.1.2	DATE	2026. 01. 24

Mohamed Hassan Bokhtia

SPP21019 Pipespools Inspection after Painting (DFT CHECK):
Dry Film Thickness (DFT) Check of finish coats list (Batch BP0002)

No.	Trace No.	Spool No.	Barcode	Paint code	Area2	Package No.	Shipment	Material	QTY
1	A03857	114-LNG-0417/191-S04	PSPP2101903987	8	22.349	GDWP010000000814	1	SS	1
2	D00133	114-LNG-0417/191-S05	PSPP2101903988	8	22.33	GDWP010000000814	1	SS	1
3	A19362	114-LNG-0417/191-S06	PSPP2101903989	8	22.33	GDWP010000000814	1	SS	1
4	A07628	114-LNG-0417/191-S07	PSPP2101903990	8	22.29	GDWP010000000814	1	SS	1
5	A09453	114-LNG-0417/191-S08	PSPP2101903991	8	7.959	GDWP010000000814	1	SS	1
6	A16118	114-LNG-0417/191-S13	PSPP2101903996	8	22.273	GDWP010000000814	1	SS	1

119.53