

SETUP SEQUENCE

- ✓

Autopilot Setup

Welcome & Overview
- ✓

Customer Passport

Select Account
- ✓

Machine Passport

ESI 5330 Flex
- ✓

Session Detection

Session Found
- MHC Journey Rail

Day 4 — 09_report

- WORKFLOW SCHEDULE11% READY
- ✓

01 Laser Hours

DAY 1
- ▮

02 Laser System Calibration

DAY 1

└─ Laser Power (Laser 1 & 2)

└─ Beam Profile / Mode (Laser 1 & 2)

└─ Laser Optics & Head Inspection
- ▮

04 Stage Calibration

DAY 2

└─ Stage 1

└─ Stage 2
- ▮

05 AGC

DAY 3

└─ AGC 1

└─ AGC 2
- ✓

06 Temperature & Evidence

DAY 3
- ✓

07 Recommendations & Spare Parts

DAY 4
- ✓

08 MHC Readiness Review

DAY 4
- 09 Report Generation

DAY 4
- ▮

10 Buyoff / Complete

DAY 4

ESI 5330 Flex (WLVIA#3)

Customer: Cleanroom Customer • Plant: • Start Date: 2026-09-02

MHC Readiness Analysis

11% Complete

COMPLETED1 / 9

CURRENT DAYDAY 4

NEEDS REVIEW0 Items

REPORT STATUSPENDING CORE

FSOSv1.2.8 • OFFICIAL MHC PDF

Full Report Engine Preview (8 Pages)

MHC-SN-98765-2026 • ESI 5330 Flex (WLVIA#3)

Edit Metadata

90%

Hide Empty

Print

Download Official MHC PDF

Test Option B (200 DPI)

Proceed to Buyoff / Complete (09) →

Back

CONFIDENTIAL TECHNICAL REPORT

Maintenance & Health Check (MHC) Report

System Health, Calibration & Optical Performance Assessment

MACHINE & CUSTOMER IDENTITY		MHC EVALUATION & ASSESSMENT	
CUSTOMER ACCOUNT	Acme PCB Corp	PLANT / FACILITY	Plant 2 - Penang
PRODUCTION LINE	—	ZONE	—
MACHINE MODEL	ESI 5330 Flex	MACHINE NUMBER / SOURCE	WLVIA#3
SERIAL NUMBER	SN-98765		
BASELINE DATE	—	LAST MHC DATE	2026-09-02

02 TABLE OF CONTENTS / REPORT INDEX

14 Subsystem Diagnostics & Certification Modules

REPORT INDEX

MHC EVALUATION

⊗ ACTION_REQUIRED

—

— NOT COLLECTED

1 HEADS ANALYZED

 PASS

20,000 hrs (EOL)

TELEMETRY VERIFICATION
Physical Counter Verified

PROGNOSTIC ADVISORY

Laser Head 1: Mid-to-late life phase (28.7% remaining). Tube capacity is stable. Monitor optical power decay during regular service.