	Client / Company Name	Arles/Ophelia Gonzales PS
	Year / Make / Model	2013 Toyota Innova
	Plate / Conduction	WRI 617
	Transmission	Manual Transmission
	Mileage(Kms)	42891 km
Carmudi	Date Inspected	October 9, 2017
Inspection Form	Mechanic Name	Jonh Ralfh Gata
1 01111	Total Passed	130
	Total for Repair	4
	Total for Replacement	2
	Total N/A	36
	Total Inspection Points	172
EXTERIOR	38	
PASSED	28	
REPAIR	4	
REPLACEMENT	0	
N/A	6	
BODY PANELS AND BUMPERS		
No Evidence of Flood Damage	Passed	Clear
No Evidence of Fire Damage	Passed	Clear
No Evidence of Major Damage	Passed	Clear
No Evidence of Hail Damage	Passed	Clear
Body Panel Inspection	Repair	Front Passenger Side Door/Fender (Dent)

Bumper/Fascia	Repair	Rear/Front bumper (Scratched)
Inspection	·	, ,
Faded Paint	Passed	Ok
Different Shade / Color Panel	Passed	Ok
Different size panel gaps	Passed	Ok
Loose or missing trim pieces	Passed	Ok
Evidence of poorly repaired accident damage	Passed	Ok
Small rust spots	Passed	Ok
DOORS, HOOD, DECKLID, TAILGATE		
Doors Inspection/Alignment	Passed	Ok
Hood Inspection/Alignment	Repair	Dent
Decklid Inspection/Alignment	N/A	
Tailgate Inspection/Alignment	Passed	Ok
Roof Inspection	Passed	Ok
Hood Release Mechanisms Operate Properly	Passed	Ok
Hood Hinges Operate Properly	Passed	Ok
Hood Prop Rod/Gas Struts Operate Properly	Passed	Ok
Door Hinges Operate Properly	Passed	Ok
Trunk/Tailgate Hinges/Gas Struts Operate Properly	Passed	Ok
GRILLE, TRIM AND ROOF RACK		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok
Roof Rack Inspection	N/A	

Deployable Running Boards	N/A	
GLASS AND OUTSIDE MIRRORS		
Windshield Glass Inspection	Passed	Ok
Side Glass Inspection	Passed	Ok
Rear Window/Tailgate Glass Inspection	Passed	Ok
Wiper Blade Replacement	Passed	Ok
Outside Mirror Inspection	Passed	Ok
Outside Folding Mirror Inspection	Passed	Ok
EXTERIOR LIGHTS		
Front-End Exterior Lights	Passed	Ok
Back-End Exterior Lights	Repair	Check bulb or electrical wiring (Brake light passenger side)
Side Exterior Lights	N/A	
Hazard Lights	Passed	Ok
Auto On/Off Lighting	N/A	
Trailer Lamp Connector Operation	N/A	
INTERIOR	63	
PASSED	44	
REPAIR	0	
REPLACEMENT	0	
N/A	19	
CONVENIENCE		
Owner's Guide	Passed	Ok
Keys and Remote Controls	Passed	Ok
AIRBAG AND SAFETY BELTS		
Airbags	Passed	Ok
Safety Belts	Passed	Ok

AUDIO AND ALARM		
SYSTEMS		
Radio, Cassette, CD and Speakers	Passed	Ok
Antenna	Passed	Ok
Alarm/Theft-Deterrent System	N/A	
Navigation System	N/A	
HEAT/VENT/AC/DEFO G/DEFROST		
Air Conditioning System	Passed	Ok
Heating System	N/A	
Defog/Defrost	Passed	Ok
INTERIOR AMENITIES		
Clock	Passed	Ok
Tilt/Telescopic Steering Wheel	Passed	Ok
Steering Column Lock	Passed	Ok
Steering Wheel Controls	Passed	Ok
Horn	Passed	Ok
Warning Chimes	Passed	Ok
Instrument Panel and Warning Lights	Passed	Ok
Windshield Wipers	Passed	Ok
Rear Window Wiper	Passed	Ok
Washers	Passed	Ok
Interior Courtesy, Dome and Map Lights	Passed	Ok
Outside Rearview Mirrors	Passed	Ok
Auto-Dimming Rearview Mirror	N/A	
Rear View Camera System)	N/A	
Active Park Assist	Passed	Ok
Rear Entertainment System	N/A	

Power Outlets	Passed	Ok
Lighter	Passed	Ok
Ashtrays	Passed	Ok
Glove Box	Passed	Ok
Center	Passed	Ok
Armrest/Console		
Sun Visors, Vanity Mirror and Light	Passed	Ok
Adjustable Pedals (if equipped)	N/A	
CARPET, TRIM AND		
MATS		
Interior Odor-Free	Passed	Ok
Carpet	Passed	Ok
Floor Mats	Passed	Ok
Door Trim and Door Panels	Passed	Ok
Headliner	Passed	Ok
SEATS		
Seat Upholstery	Passed	Ok
Seat and Head Restraint Adjustment	Passed	Ok
Folding Seats	Passed	Ok
Heated Seats	N/A	
Cooled Seats	N/A	
Integrated Child Safety Seats	N/A	
SUNROOF/MOONRO OF/CONVERTIBLE TOP		
Sunroof/Moonroof	N/A	
Convertible Top	N/A	
WINDOWS AND DOOR LOCKS		
Door Handles and Release Mechanisms	Passed	Ok
Remote Entry System	Passed	Ok

Door Locks	Push-Button Start System	N/A	
Window Controls Remote Decklid Release Fuel Filler Door Release Fuel Filler Door Release COMPARTMENT Luggage Compartment Carpet Luggage Compartment Trim and Cargo Net Luggage Compartment Trim and Cargo Net Luggage Compartment Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Tire Inflator Kit Emergency Trunk-Lid Release DIAGNOSTICS 1 REPAIR REPLACEMENT N/A OMDDULE SYSTEM TEST Perform Self-Test for all CMDTCs UNDERHOOD 35	Door Locks	Passed	Ok
Remote Decklid Release Fuel Filler Door Release Fuel Filler Door Release COMPARTMENT Luggage Compartment Carpet Luggage Compartment Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Tire Inflator Kit Emergency Trunk-Lid Release DIAGNOSTICS 1 REPAIR REPLACEMENT N/A  MODULE SYSTEM TEST Perform Self-Test for all CMDTCs UNDERHOOD 35	Child Safety Locks	Passed	Ok
Release Fuel Filler Door Release LUGGAGE COMPARTMENT Luggage Compartment Carpet Luggage Compartment Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Tire Inflator Kit Emergency Trunk-Lid Release DIAGNOSTICS PASSED 1 REPAIR 0 RMDULE SYSTEM TEST Perform Self-Test for all CMDTCS UNDERHOOD 35	Window Controls	Passed	Ok
Release  LUGGAGE COMPARTMENT  Luggage Compartment Carpet  Luggage Compartment Trim and Cargo Net Luggage Compartment/Cargo Area Light  Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Tire Inflator Kit Emergency Trunk-Lid Release DIAGNOSTICS  1  REPAIR 0  REPLACEMENT N/A  MODULE SYSTEM TEST Perform Self-Test for all CMDTCS UNDERHOOD  N/A  N/A  N/A  N/A  N/A  N/A  RISSED  AUGUST A Clear  OK  N/A  Passed Ok  Ok  Ok  Ok  Ok  Ok  Ok  Ok  Ok  Ok		N/A	
COMPARTMENT  Luggage Compartment Carpet  Luggage Compartment Trim and Cargo Net  Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Tire Inflator Kit Emergency Trunk-Lid Release DIAGNOSTICS 1 PASSED 1 REPAIR 0 REPLACEMENT N/A 0 MODULE SYSTEM TEST Perform Self-Test for all CMDTCS UNDERHOOD 35	Release	Passed	Ok
Luggage Compartment Carpet Luggage Compartment Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Tire Inflator Kit Emergency Trunk-Lid Release DIAGNOSTICS 1 REPAIR REPLACEMENT N/A  MODULE SYSTEM TEST Perform Self-Test for all CMDTCs UNDERHOOD  N/A  N/A  N/A  N/A  N/A  N/A  N/A  N/			
Carpet Luggage Compartment Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Tire Inflator Kit Emergency Trunk-Lid Release DIAGNOSTICS 1 PASSED 1 REPAIR 0 REPLACEMENT N/A  MODULE SYSTEM TEST Perform Self-Test for all CMDTCS UNDERHOOD  N/A  N/A  N/A  N/A  N/A  N/A  N/A  N/			
Trim and Cargo Net Luggage Compartment/Cargo Area Light Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Tire Inflator Kit Emergency Trunk-Lid Release DIAGNOSTICS I PASSED I REPAIR O REPLACEMENT N/A  MODULE SYSTEM TEST Perform Self-Test for all CMDTCS UNDERHOOD  N/A  N/A  Passed Ok Ok Ok  N/A  Passed Ok  N/A  N/A  Passed Ok  N/A  Diagnostics Passed Ok  N/A  Clear  Clear	Carpet	N/A	
Compartment/Cargo Area Light  Vehicle Jack, Tool Kit, Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection  Tire Inflator Kit Emergency Trunk-Lid Release  DIAGNOSTICS  1  REPAIR  0  REPLACEMENT  N/A  MODULE SYSTEM TEST Perform Self-Test for all CMDTCs UNDERHOOD  N/A  Passed  Ok Ok  Ok  N/A  Passed Ok  N/A  N/A  Passed Ok  N/A  N/A  Passed Ok  N/A  Ok  Ok  Ok  Ok  Ok  Ok  Ok  Ok  Ok  O	Trim and Cargo Net	N/A	
Early Warning Device Spare Tire Size/Type and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Tire Inflator Kit Emergency Trunk-Lid Release DIAGNOSTICS 1 PASSED 1 REPAIR 0 REPLACEMENT N/A 0 MODULE SYSTEM TEST Perform Self-Test for all CMDTCs UNDERHOOD 35	Compartment/Cargo Area Light	N/A	
and Sidewall Inspection Spare Tire Tread Depth/Air Pressure Inspection Tire Inflator Kit Emergency Trunk-Lid Release DIAGNOSTICS 1 PASSED 1 REPAIR 0 REPLACEMENT N/A 0 MODULE SYSTEM TEST Perform Self-Test for all CMDTCs UNDERHOOD 35	Early Warning Device	Passed	Ok
Depth/Air Pressure Inspection  Tire Inflator Kit  Emergency Trunk-Lid N/A  Emergency Trunk-Lid N/A  PASSED  I  REPAIR  O  REPLACEMENT  N/A  MODULE SYSTEM TEST  Perform Self-Test for all CMDTCs  UNDERHOOD  Ok  N/A  N/A  Passed  Ok  N/A  N/A  N/A  N/A  Passed  Clear		Passed	Ok
Emergency Trunk-Lid Release  DIAGNOSTICS  1  PASSED  1  REPAIR  0  REPLACEMENT  N/A  0  MODULE SYSTEM TEST  Perform Self-Test for all CMDTCs  UNDERHOOD  35	Depth/Air Pressure	Passed	Ok
DIAGNOSTICS	Tire Inflator Kit	N/A	
PASSED         1           REPAIR         0           REPLACEMENT         0           N/A         0           MODULE SYSTEM TEST         TEST           Perform Self-Test for all CMDTCs         Passed         Clear           UNDERHOOD         35		N/A	
REPAIR         0           REPLACEMENT         0           N/A         0           MODULE SYSTEM TEST         Perform Self-Test for all CMDTCs           Perform Self-Test for all CMDTCs         Passed           UNDERHOOD         35	DIAGNOSTICS	1	
REPLACEMENT 0  N/A 0  MODULE SYSTEM TEST  Perform Self-Test for all CMDTCs  UNDERHOOD 35	PASSED	1	
N/A 0  MODULE SYSTEM TEST  Perform Self-Test for all CMDTCs  UNDERHOOD 35	REPAIR	0	
MODULE SYSTEM TEST  Perform Self-Test for all CMDTCs  UNDERHOOD  35	REPLACEMENT	0	
TEST Perform Self-Test for all CMDTCs Passed Clear UNDERHOOD 35	N/A	0	
CMDTCs Passed Clear UNDERHOOD 35	TEST		
		Passed	Clear
PASSED 29	UNDERHOOD	35	
	PASSED	29	

REPAIR	0	
REPLACEMENT	0	
N/A	6	
FLUIDS		
Engine Oil/Filter Change	Passed	Ok
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmission Fluid	N/A	
Transfer Case Fluid	Passed	Ok
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	Passed	Ok
Manual Transaxle/Transmission Hydraulic Clutch Fluid	Passed	Ok
Washer Fluid	Passed	Ok
ENGINE		
Fluid Leaks	Passed	Ok
Hoses, Lines and Fittings	Passed	Ok
Belts	Passed	Ok
Wiring	Passed	Ok
Oil in Air Cleaner Housing	Passed	Ok
Water, Sludge or Engine Coolant in Oil	Passed	Ok
Oil Pressure	Passed	Ok
Relative Cylinder Compression Test/Power Balance Readings (check if necessary)	N/A	Untested
Timing Belt	N/A	Untested
Engine Mounts	Passed	Ok
Inspect Turbocharger Air Cooler	N/A	

COOLING SYSTEM		
Radiator	Passed	Ok
Pressure-Test Radiator Cap and Radiator	N/A	Untested
Cooling Fans, Clutches and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery Tank	Passed	Ok
Cabin Air Filter	N/A	
FUEL SYSTEM		
Fuel Pump Noise Normal	Passed	Ok
Fuel Pump Pressure	Passed	Ok
Fuel Filter	Passed	Ok
Engine Air Filter	Passed	Ok
ELECTRICAL SYSTEM		
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	12.42 v
Alternator Output	Passed	13.53 v
Diesel Glow Plug System	Passed	Ok
UNDER CHASSIS	35	
PASSED	28	
REPAIR	0	
REPLACEMENT	2	
N/A	5	
FRAME		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
EXHAUST SYSTEM		
Exhaust System Condition	N/A	Untested
Emissions Control Test	N/A	Untested

TRANSMISSION,		
TRANSAXLE,		
DIFFERENTIAL AND		
TRANSFER CASE		
Automatic	N/A	
Transmission/Transaxle		
Manual Transmission/Transaxle		
. Differential and	Passed	Ok
Transfer Case		
4x4 Hub Operation	N/A	
Universal Joints, CV		
Joints and CV Joint	Passed	Ok
Boots		
Transmission Mounts (not cracked, broken or	Passed	Ok
oil-soaked)	rasseu	OK
Differential/Drive Axle	Passed	Ok
TIRES AND WHEELS		
Tires Match and Are	Desced	205/65045
Correct Size	Passed	205/65R15
Wheels Match and Are	Passed	Correct Wheel Size
Correct Size		
Tire Tread Depth – Front Tires (L/R)	Replace	Left Ok/Right Replace (Required for Tire Rotation)
Tire Tread Depth –		Left Ok/Right Replace (Required for
Rear Tires (L/R)	Replace	Tire Rotation)
Normal Tire Wear	Passed	Normal
Tire Pressure – Front	Passed	32psi
Tires (L/R)	rasseu	32psi
Tire Pressure – Rear	Passed	33psi
Tires (L/R) Tire Pressure		<u>'</u>
Monitoring System	N/A	
No Evidence of Wheel		
Curb Damage	Passed	Ok
Wheel Covers and	Passed	Complete
Center Caps	1 03360	Complete
Rack-and-Pinion,	Passed	Ok
Linkage and Boots		-
Control Arms, Bushings and Ball Joints	Passed	Ok
מווע טמוו טטווונס		

Tie Rods and Idler Arm	Passed	Ok
Sway Bars, Links and Bushings	Passed	Ok
Springs	Passed	Ok
Struts and Shocks	Passed	Ok
Wheel Alignment (check if necessary)	Passed	Ok
Power Steering Pump	Passed	Ok
BRAKES		
Calipers and Wheel Cylinders	Passed	Ok
Brake Pads and Shoes  – Front Brakes (L/R)	Passed	Ok
Brake Pads and Shoes  – Rear Brakes (L/R)	Passed	Ok
Rotors and Drums	Passed	Ok
Brake Lines, Hoses and Fittings	Passed	Ok
Parking Brake	Passed	Ok
Master Cylinder and Booster	Passed	Ok