Carmudi Inspection	Client / Company Name	Auto Fairway Car Exchange
	Year / Make / Model	2009 Kia Carnival
	Plate / Conduction	NJO 788
	Transmission	Automatic Transmission
	Mileage(Kms)	71886
Form	Date Inspected	May 3, 2017
	Mechanic Name / Signature	Ralfh Gata
	Overall Score	134
	Overall Total	173
EXTERIOR	38	
PASSED	32	
BODY PANELS AND BUMPERS		
No Evidence of Flood	Passed	Cleared
Damage No Evidence of Fire		Cleared
Damage No Evidence of Major	Passed	
Damage	Passed	Cleared
No Evidence of Hail Damage	Passed	Cleared
Body Panel Inspection	Repair	Scratches (Front Door Passenger
Bumper/Fascia Inspection	Passed	Ok
Faded Paint	Passed	Ok
Different Shade / Color Panel	Passed	Ok
Different size panel	Passed	Ok
Loose or missing trim pieces	Passed	Ok
Evidence of poorly repaired accident damage	Passed	Ok
Small rust spots	Passed	Ok
DOORS, HOOD, DECKLID, TAILGATE		
Doors Inspection/Alignment	Passed	Ok
Hood Inspection/Alignment	Passed	Ok
Decklid	N/A	
Inspection/Alignment Tailgate	Passed	Ok
Inspection/Alignment Roof Inspection	Passed	Ok
Hood Release Mechanisms Operate	Passed	Ok
Properly Hood Hinges Operate	Deced	Ok
Properly Hood Prop Rod/Gas	Passed	Ok
Struts Operate Properly	Passed	Ok
Door Hinges Operate Properly	Passed	Ok
Trunk/Tailgate Hinges/Gas Struts Operate Properly	Passed	Ok
GRILLE, TRIM AND ROOF RACK		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok
Roof Rack Inspection	N/A	

N/A	
Passed	Ok
Replace	Scratched (Rear Window)
Passed	Ok
Passed	Ok
Passed	Ok
	Ok
rasseu	OK .
Passed	Ok
N/A	
64	
44	
N/A	
Passed	Ok
N/A	
Passed	Without Passenger Airbag
Passed	Ok
Passed	Ok
Passed	Ok
N/A	Ok
N/A	
Passed	Ok
Passed	Ok
Passed	Ok
Passed	Ok
Passed	Ok
	Passed Replace Passed N/A N/A Passed

Outside Rearview		01
Mirrors	Passed	Ok
Auto-Dimming Rearview Mirror	Passed	Ok
Rear View Camera System)	N/A	
Active Park Assist	Passed	Ok
Rear Entertainment System	N/A	
Power Outlets	Passed	Ok
Lighter	Passed	Ok
Ashtrays	Passed	Ok
Glove Box	Passed	Ok
Center	Passed	Ok
Armrest/Console Sun Visors, Vanity	Passed	Ok
Mirror and Light Adjustable Pedals (if		O.K
equipped) CARPET, TRIM AND	N/A	
MATS		
Interior Odor-Free	Passed	Ok
Carpet	Passed	Ok
Floor Mats	Passed	Ok
Door Trim and Door Panels	Passed	Ok
Headliner	Passed	Ok
SEATS		
Seat Upholstery	Passed	Ok
Seat and Head Restraint Adjustment	Passed	Ok
Folding Seats	Passed	Ok
Heated Seats	N/A	
Cooled Seats	N/A	
Integrated Child Safety	N/A	
Seats SUNROOF/MOONRO		
OF/CONVERTIBLE TOP		
Sunroof/Moonroof	N/A	
Convertible Top	N/A	
WINDOWS AND DOOR LOCKS		
Door Handles and Release Mechanisms	Repair	Mechanism (Front Door Passenge
Remote Entry System	Passed	Ok
Push-Button Start	N/A	
System Door Locks	Passed	Ok
Child Safety Locks	Passed	Ok
Window Controls	Passed	Ok
Remote Decklid	N/A	On On
Release Fuel Filler Door		
Release LUGGAGE	Passed	Ok
COMPARTMENT		
Luggage Compartment Carpet	N/A	
Luggage Compartment Trim and Cargo Net	N/A	
Luggage Compartment/Cargo Area Light	N/A	
Vehicle Jack and Tool Kit	Passed	Ok
Spare Tire Size/Type and Sidewall Inspection	Passed	Ok

Spare Tire Tread Depth/Air Pressure Inspection	Passed	Ok
Tire Inflator Kit	N/A	
Emergency Trunk-Lid Release	Passed	Ok
DIAGNOSTICS	1	
PASSED	0	
MODULE SYSTEM TEST		
Perform Self-Test for	N/A	Untested
all CMDTCs UNDERHOOD	35	5 11105104
PASSED	29	
FLUIDS		
Engine Oil/Filter Change	Passed	Ok
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmissio n Fluid	Replace	Requires Change ATF
Transfer Case Fluid	Passed	Ok
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	Passed	Ok
Manual	. 45554	<u> </u>
Transaxle/Transmissio n Hydraulic Clutch Fluid	N/A	
Washer Fluid	Passed	Ok
ENGINE		
Fluid Leaks	Passed	Ok
Hoses, Lines and	Passed	Ok
Fittings Belts	Passed	Ok
Wiring	Passed	Ok
Oil in Air Cleaner	Passed	Ok
Housing Water, Sludge or		
Engine Coolant in Oil	Passed	Ok
Oil Pressure	Passed	Ok
Relative Cylinder Compression Test/Power Balance Readings (check if necessary)	N/A	Untested
Timing Belt	N/A	Untested
Engine Mounts	Passed	Ok
Inspect Turbocharger Air Cooler	N/A	
COOLING SYSTEM		
Radiator	Passed	Ok
Pressure-Test Radiator Cap and Radiator	Passed	Ok
Cooling Fans, Clutches and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery	Passed	Ok
Cabin Air Filter	Passed	Ok
FUEL SYSTEM		
Fuel Pump Noise	Passed	Ok
Normal Fuel Pump Pressure	Passed	Ok
·	Passed	Ok
Fuel Filter	rassed	UK

Engine Air Eilter	Poplaco	
Engine Air Filter ELECTRICAL	Replace	
SYSTEM		
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	12.27 v
Alternator Output	Passed	13.40 v
Diesel Glow Plug System	Passed	Ok
UNDER CHASSIS	35	
PASSED	29	
FRAME		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
EXHAUST SYSTEM		
Exhaust System Condition	N/A	
Emissions Control Test	N/A	
TRANSMISSION, TRANSAXLE, DIFFERENTIAL AND TRANSFER CASE Automatic		
Transmission/Transaxl e	Passed	Ok
Manual Transmission/Transaxl e, Differential and Transfer Case	N/A	
4x4 Hub Operation	N/A	
Universal Joints, CV Joints and CV Joint Boots	Passed	Ok
Transmission Mounts (not cracked, broken or oil-soaked)	Passed	Ok
Differential/Drive Axle	Passed	Ok
TIRES AND WHEELS		
Tires Match and Are Correct Size	Passed	R17
Wheels Match and Are Correct Size	Passed	Ok
Tire Tread Depth –	Passed	3 mm
Front Tires (L/R) Tire Tread Depth –	Passed	3 mm
Rear Tires (L/R) Normal Tire Wear	Passed	Normal
Tire Pressure – Front	Passed	30 psi
Tires (L/R) Tire Pressure – Rear		·
Tires (L/R) Tire Pressure	Passed	30 psi
Monitoring System	N/A	
No Evidence of Wheel Curb Damage	Passed	Ok
Wheel Covers and Center Caps	Passed	Ok
Rack-and-Pinion, Linkage and Boots	Passed	Ok
Control Arms, Bushings and Ball Joints	Passed	Ok
Tie Rods and Idler Arm	Passed	Ok
Sway Bars, Links and Bushings	Passed	Ok
Springs	Passed	Ok
Struts and Shocks	Passed	Ok
Wheel Alignment (check if necessary)	Passed	Ok Based on Tire Wear
Power Steering Pump	Passed	Ok

BRAKES		
Calipers and Wheel Cylinders	Passed	Ok
Brake Pads and Shoes – Front Brakes (L/R)	Passed	Ok
Brake Pads and Shoes – Rear Brakes (L/R)	Passed	Ok
Rotors and Drums	Repair	tor Disc Refacing (Rear Wheel Pas
Brake Lines, Hoses and Fittings	Passed	Ok
Parking Brake	Passed	Ok
Master Cylinder and Booster	Passed	Ok