Carmudi Inspection Form	Client / Company Name	Elmer Chan/Auto Express
	Year / Make / Model	2013 SCION FR-S
	Plate / Conduction	VDY 909
	Transmission	Manual Transmission
	Mileage(Kms)	2000 Miles
	Date Inspected	June 1, 2017
	Mechanic Name / Signature	Ralfh Gata
	Overall Score	139
	Overall Total	173
EXTERIOR	38	
PASSED	33	
BODY PANELS AND BUMPERS		
No Evidence of Flood	Passed	Cleared
Damage No Evidence of Fire	Passed	Cleared
Damage No Evidence of Major		
Damage	Passed	Cleared
No Evidence of Hail Damage	Passed	Cleared
Body Panel Inspection	Passed	Ok
Bumper/Fascia Inspection	Passed	Ok
Faded Paint	Passed	Ok
Different Shade / Color Panel	Passed	Ok
Different size panel	Passed	Ok
Loose or missing trim pieces	Passed	Ok
Evidence of poorly repaired accident damage	Passed	Ok
Small rust spots	Passed	Ok
DOORS, HOOD, DECKLID, TAILGATE		
Doors	Passed	Ok
Inspection/Alignment Hood	Passed	Ok
Inspection/Alignment Decklid		Ok
Inspection/Alignment Tailgate	Passed	-
Inspection/Alignment	N/A	Ok
Roof Inspection Hood Release	Passed	Ok
Mechanisms Operate Properly	Passed	Ok
Hood Hinges Operate Properly	Passed	Ok
Hood Prop Rod/Gas Struts Operate Properly	Passed	Ok
Door Hinges Operate Properly	Passed	Ok
Trunk/Tailgate Hinges/Gas Struts Operate Properly	Passed	Ok
GRILLE, TRIM AND ROOF RACK		
Grille Inspection	Passed	Ok
Trim Inspection	Passed	Ok
Roof Rack Inspection	N/A	
,		

N/A	
	21
Passed	Ok
Passed	Ok
Passed	Ok
	Ok
	Ok
	OK
64	
48	
Passed	Ok
Passed	Ok
Replace	1/4 Tank Need to Refill
Passed	With Passenger Airbag
Passed	Ok
Passed	Ok
Passed	Ok
Passed	Ok
N/A	
Passed	Ok
	Ok
Passed	Ok
	<u> </u>
Doggod	Ok
	Ok
	Ok
Passed	Ok
Passed	Ok
Passed	Ok
Passed	Ok
Passed Passed	Ok Ok
	-
Passed	Ok
Passed Passed	Ok
	Passed

Outside Rearview		
Mirrors	Passed	Ok
Auto-Dimming Rearview Mirror	N/A	
Rear View Camera System)	N/A	
Active Park Assist	N/A	
Rear Entertainment System	N/A	
Power Outlets	Passed	Ok
Lighter	Passed	Ok
Ashtrays	Passed	Ok
Glove Box	Passed	Ok
Center Armrest/Console	Passed	Ok
Sun Visors, Vanity Mirror and Light	Passed	Ok
Adjustable Pedals (if	N/A	
equipped) CARPET, TRIM AND		
MATS Interior Odor-Free	Passed	Ok
		Ok
Carpet	Passed	
Floor Mats Door Trim and Door	Passed	Ok
Panels	Passed	Ok
Headliner	Passed	Ok
SEATS		
Seat Upholstery	Passed	Ok
Seat and Head Restraint Adjustment	Passed	Ok
Folding Seats	Passed	Ok
Heated Seats	N/A	
Cooled Seats	N/A	
Integrated Child Safety Seats	N/A	
SUNROOF/MOONRO OF/CONVERTIBLE TOP		
Sunroof/Moonroof	N/A	
Convertible Top	N/A	
WINDOWS AND DOOR LOCKS		
Door Handles and Release Mechanisms	Passed	Ok
Remote Entry System	Passed	Ok
Push-Button Start	N/A	
System Door Locks	Passed	Ok
Child Safety Locks	Passed	Ok
Window Controls	Passed	Ok
Remote Decklid	N/A	-
Release Fuel Filler Door		Ok
Release LUGGAGE	Passed	OK .
COMPARTMENT Luggage Compartment		
Carpet	Passed	Ok
Luggage Compartment Trim and Cargo Net	Passed	Ok
Luggage Compartment/Cargo Area Light	Passed	Ok
Vehicle Jack and Tool Kit	Passed	Ok
Spare Tire Size/Type and Sidewall Inspection	Passed	Ok

Spare Tire Tread Depth/Air Pressure Inspection	Passed	Ok
Tire Inflator Kit	N/A	
Emergency Trunk-Lid Release	Passed	Ok
DIAGNOSTICS	1	
PASSED	0	
MODULE SYSTEM TEST		
Perform Self-Test for all CMDTCs	N/A	Untested
UNDERHOOD	35	
PASSED	29	
FLUIDS		
Engine Oil/Filter Change	Passed	Ok
Coolant	Passed	Ok
Brake Fluid	Passed	Ok
Automatic Transaxle/Transmissio	N/A	Manual Transmission
n Fluid Transfer Case Fluid	Doggod	Ok
	Passed	
Drive Axle Fluid	Passed	Ok
Power Steering Fluid	N/A	Electronic
Manual Transaxle/Transmissio n Hydraulic Clutch Fluid	Passed	OI
Washer Fluid	Passed	Ok
ENGINE		
Fluid Leaks	Passed	Ok
Hoses, Lines and	Passed	Ok
Fittings Belts	Passed	Ok
Wiring	Passed	Ok
Oil in Air Cleaner Housing	Passed	Ok
Water, Sludge or	Passed	Ok
Engine Coolant in Oil Oil Pressure	Passed	Ok
Relative Cylinder Compression Test/Power Balance Readings (check if necessary)	N/A	<u> </u>
Timing Belt	N/A	
Engine Mounts	Passed	Ok
Inspect Turbocharger Air Cooler	N/A	
COOLING SYSTEM		
Radiator	Passed	Ok
Pressure-Test Radiator Cap and Radiator	Passed	Ok
Cooling Fans, Clutches and Motors	Passed	Ok
Water Pump	Passed	Ok
Coolant Recovery Tank	Passed	Ok
Cabin Air Filter	Passed	Ok
FUEL SYSTEM		
Fuel Pump Noise Normal	Passed	Ok
Fuel Pump Pressure	Passed	Ok
Fuel Filter	Passed	Ok
<u> </u>		

Engine Air Filter	Danaad	Ok
Engine Air Filter ELECTRICAL	Passed	Ok
SYSTEM		
Starter Operation	Passed	Ok
Ignition System	Passed	Ok
Battery	Passed	12.38 v
Alternator Output	Passed	14.35 v
Diesel Glow Plug System	N/A	Petrol Engine
UNDER CHASSIS	35	
PASSED	29	
FRAME		
Frame Damage	Passed	Ok
Fuel Supply System	Passed	Ok
EXHAUST SYSTEM		
Exhaust System Condition	N/A	
Emissions Control Test	N/A	
TRANSMISSION, TRANSAXLE, DIFFERENTIAL AND TRANSFER CASE Automatic		
Transmission/Transaxl e	N/A	Manual Transmission
Manual Transmission/Transaxl e, Differential and Transfer Case	Passed	Ok
4x4 Hub Operation	N/A	
Universal Joints, CV Joints and CV Joint Boots	Passed	Ok
Transmission Mounts (not cracked, broken or oil-soaked)	Passed	Ok
Differential/Drive Axle	Passed	Ok
TIRES AND WHEELS		
Tires Match and Are Correct Size	Passed	R17
Wheels Match and Are Correct Size	Passed	Ok
Tire Tread Depth –	Passed	5mm
Front Tires (L/R) Tire Tread Depth –	Passed	5mm
Rear Tires (L/R) Normal Tire Wear	Passed	Normal
Tire Pressure – Front	Passed	30psi
Tires (L/R) Tire Pressure – Rear		
Tires (L/R) Tire Pressure	Passed	32psi
Monitoring System	N/A	
No Evidence of Wheel Curb Damage	Passed	Ok
Wheel Covers and Center Caps	Passed	Ok
Rack-and-Pinion, Linkage and Boots	Passed	Ok
Control Arms, Bushings and Ball Joints	Passed	Ok
Tie Rods and Idler Arm	Passed	Ok
Sway Bars, Links and Bushings	Passed	Ok
Springs	Passed	Ok
Struts and Shocks	Passed	Ok
Wheel Alignment (check if necessary)	Passed	Ok Based on Tire Wear
Power Steering Pump	N/A	Electronic

BRAKES		
Calipers and Wheel Cylinders	Passed	Ok
Brake Pads and Shoes - Front Brakes (L/R)	Passed	Ok
Brake Pads and Shoes - Rear Brakes (L/R)	Passed	Ok
Rotors and Drums	Passed	Ok
Brake Lines, Hoses and Fittings	Passed	Ok
Parking Brake	Passed	Ok
Master Cylinder and Booster	Passed	Ok