| Client / Company Name James Bucaneg | | | |
|--|-----------------------|-------------------------|------------------------|
| Plate / Conduction | | Client / Company Name | James Bucaneg |
| Transmission | | Year / Make / Model | 2017 TOYOTA VIOS |
| Mileage(Kms) 1609 km | | Plate / Conduction | VK 1536 |
| Carmudi Inspection Form Date Inspected July 11, 2017 Mechanic Name Ralfh Gata Total Passed 139 Total for Repair 0 Total N/A 33 Total Inspection Points 172 EXTERIOR 38 PASSED 33 REPLACEMENT 0 REPLACEMENT 0 N/A 5 BODY PANELS AND BUMPERS No Evidence of Flood Damage Passed Cleared No Evidence of Fire Damage Passed Cleared No Evidence of Major Damage Passed Cleared No Evidence of Hail Damage Passed Cleared Cleared Cleared | | Transmission | Automatic Transmission |
| Date Inspected July 11, 2017 | 0 | Mileage(Kms) | 1609 km |
| Total Passed | | Date Inspected | July 11, 2017 |
| Total Passed 139 | | Mechanic Name | Ralfh Gata |
| Total for Replacement | 1 01111 | Total Passed | 139 |
| Total N/A Total Inspection Points 172 EXTERIOR PASSED 33 REPAIR 0 REPLACEMENT 0 N/A 5 BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared Cleared Cleared Cleared Cleared | | Total for Repair | 0 |
| Total Inspection Points 172 EXTERIOR 38 PASSED 33 REPAIR 0 REPLACEMENT 0 N/A 5 BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared No Evidence of Hail Damage Cleared Passed Cleared Cleared Cleared Cleared Cleared Cleared Cleared Cleared | | Total for Replacement | 0 |
| EXTERIOR 38 PASSED 33 REPAIR 0 REPLACEMENT 0 N/A 5 BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Major Damage No Evidence of Hail Damage No Evidence of Hail Damage No Evidence of Hail Damage No Evidence of Hail Damage Replace 33 Cleared Cleared Cleared Cleared Cleared Cleared Cleared Cleared | | Total N/A | 33 |
| PASSED REPLACEMENT 0 REPLACEMENT 0 N/A 5 BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared | | Total Inspection Points | 172 |
| PASSED REPLACEMENT 0 REPLACEMENT 0 N/A 5 BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared | | | |
| REPLACEMENT 0 N/A 5 BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared Cleared Cleared Cleared Cleared Cleared Cleared | EXTERIOR | 38 | |
| REPLACEMENT 0 N/A 5 BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared Cleared Cleared Cleared Cleared Cleared | PASSED | 33 | |
| N/A BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared Cleared Cleared Cleared | REPAIR | 0 | |
| BODY PANELS AND BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Passed Cleared Cleared Cleared Cleared Cleared Cleared Cleared | REPLACEMENT | 0 | |
| BUMPERS No Evidence of Flood Damage No Evidence of Fire Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared Cleared Cleared Cleared Cleared Cleared | N/A | 5 | |
| No Evidence of Flood Damage No Evidence of Fire Damage Passed Cleared Cleared Cleared Cleared Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared | | | |
| Damage No Evidence of Fire Damage No Evidence of Major Damage Passed Passed Cleared | | | |
| Damage No Evidence of Major Damage No Evidence of Hail Damage Passed Cleared Cleared Cleared Cleared Cleared | | Passed | Cleared |
| Damage Passed Cleared No Evidence of Hail Damage Passed Cleared | | Passed | Cleared |
| No Evidence of Hail Damage Passed Cleared | No Evidence of Major | Passed | Cleared |
| | No Evidence of Hail | Passed | Cleared |
| Body Panel Inspection Passed Ok | Body Panel Inspection | Passed | Ok |

| D (E : | | |
|---|--------|----|
| Bumper/Fascia Inspection | Passed | Ok |
| Faded Paint | Passed | Ok |
| Different Shade / Color Panel | Passed | Ok |
| Different size panel gaps | Passed | Ok |
| Loose or missing trim pieces | Passed | Ok |
| Evidence of poorly repaired accident damage | Passed | Ok |
| Small rust spots | Passed | Ok |
| DOORS, HOOD, DECKLID, TAILGATE | | |
| Doors Inspection/Alignment | Passed | Ok |
| Hood Inspection/Alignment | Passed | Ok |
| Decklid Inspection/Alignment | Passed | Ok |
| Tailgate Inspection/Alignment | N/A | |
| Roof Inspection | Passed | Ok |
| Hood Release Mechanisms Operate Properly | Passed | Ok |
| Hood Hinges Operate Properly | Passed | Ok |
| Hood Prop Rod/Gas Struts Operate Properly | Passed | Ok |
| Door Hinges Operate Properly | Passed | Ok |
| Trunk/Tailgate Hinges/Gas Struts Operate Properly | Passed | Ok |
| GRILLE, TRIM AND ROOF RACK | | |
| Grille Inspection | Passed | Ok |
| Trim Inspection | Passed | Ok |
| Roof Rack Inspection | N/A | |

| Deployable Running Boards | N/A | |
|---------------------------------------|--------|-----------------------|
| GLASS AND OUTSIDE MIRRORS | | |
| Windshield Glass Inspection | Passed | Ok |
| Side Glass Inspection | Passed | Ok |
| Rear Window/Tailgate Glass Inspection | Passed | Ok |
| Wiper Blade Replacement | Passed | Ok |
| Outside Mirror Inspection | Passed | Ok |
| Outside Folding Mirror Inspection | Passed | Ok |
| EXTERIOR LIGHTS | | |
| Front-End Exterior Lights | Passed | Ok |
| Back-End Exterior Lights | Passed | Ok |
| Side Exterior Lights | Passed | Ok |
| Hazard Lights | Passed | Ok |
| Auto On/Off Lighting | N/A | |
| Trailer Lamp Connector Operation | N/A | |
| INTERIOR | 63 | |
| PASSED | 47 | |
| REPAIR | 0 | |
| REPLACEMENT | 0 | |
| N/A | 16 | |
| CONVENIENCE | | |
| Owner's Guide | Passed | Ok |
| Keys and Remote Controls | Passed | Ok |
| AIRBAG AND SAFETY BELTS | | |
| Airbags | Passed | With Passenger Airbag |
| Safety Belts | Passed | Ok |

| AUDIO AND ALARM | | |
|--|--------|----|
| SYSTEMS | | |
| Radio, Cassette, CD and Speakers | Passed | Ok |
| Antenna | Passed | Ok |
| Alarm/Theft-Deterrent System | Passed | Ok |
| Navigation System | N/A | |
| HEAT/VENT/AC/DEFO G/DEFROST | | |
| Air Conditioning System | Passed | Ok |
| Heating System | N/A | |
| Defog/Defrost | Passed | Ok |
| INTERIOR AMENITIES | | |
| Clock | Passed | Ok |
| Tilt/Telescopic Steering Wheel | Passed | Ok |
| Steering Column Lock | Passed | Ok |
| Steering Wheel Controls | Passed | Ok |
| Horn | Passed | Ok |
| Warning Chimes | Passed | Ok |
| Instrument Panel and Warning Lights | Passed | Ok |
| Windshield Wipers | Passed | Ok |
| Rear Window Wiper | N/A | |
| Washers | Passed | Ok |
| Interior Courtesy, Dome and Map Lights | Passed | Ok |
| Outside Rearview Mirrors | Passed | Ok |
| Auto-Dimming Rearview Mirror | N/A | |
| Rear View Camera System) | N/A | |
| Active Park Assist | N/A | |
| Rear Entertainment System | N/A | |

| Power Outlets | Passed | Ok |
|---|--------|----|
| Lighter | Passed | Ok |
| Ashtrays | Passed | Ok |
| Glove Box | Passed | Ok |
| Center | Passed | Ok |
| Armrest/Console | | |
| Sun Visors, Vanity Mirror and Light | Passed | Ok |
| Adjustable Pedals (if equipped) | N/A | |
| CARPET, TRIM AND | | |
| MATS | | |
| Interior Odor-Free | Passed | Ok |
| Carpet | Passed | Ok |
| Floor Mats | Passed | Ok |
| Door Trim and Door Panels | Passed | Ok |
| Headliner | Passed | Ok |
| SEATS | | |
| Seat Upholstery | Passed | Ok |
| Seat and Head Restraint Adjustment | Passed | Ok |
| Folding Seats | Passed | Ok |
| Heated Seats | N/A | |
| Cooled Seats | N/A | |
| Integrated Child Safety Seats | N/A | |
| SUNROOF/MOONRO OF/CONVERTIBLE TOP | | |
| Sunroof/Moonroof | N/A | |
| Convertible Top | N/A | |
| WINDOWS AND DOOR LOCKS | | |
| Door Handles and Release Mechanisms | Passed | Ok |
| Remote Entry System | Passed | Ok |
| | | |

| Push-Button Start System | N/A | |
|---|--------|---------|
| Door Locks | Passed | Ok |
| Child Safety Locks | Passed | Ok |
| Window Controls | Passed | Ok |
| Remote Decklid Release | N/A | |
| Fuel Filler Door Release | Passed | Ok |
| LUGGAGE COMPARTMENT | | |
| Luggage Compartment Carpet | Passed | Ok |
| Luggage Compartment Trim and Cargo Net | Passed | Ok |
| Luggage Compartment/Cargo Area Light | Passed | Ok |
| Vehicle Jack, Tool Kit, Early Warning Device | Passed | Ok |
| Spare Tire Size/Type and Sidewall Inspection | Passed | Ok |
| Spare Tire Tread Depth/Air Pressure Inspection | Passed | Ok |
| Tire Inflator Kit | N/A | |
| Emergency Trunk-Lid Release | Passed | Ok |
| DIAGNOSTICS | 1 | |
| PASSED | 1 | |
| REPAIR | 0 | |
| REPLACEMENT | 0 | |
| N/A | 0 | |
| MODULE SYSTEM TEST | | |
| Perform Self-Test for all CMDTCs | Passed | Cleared |
| UNDERHOOD | 35 | |
| PASSED | 29 | |

| REPAIR | 0 | |
|--|--------|------------------------|
| REPLACEMENT | 0 | |
| N/A | 6 | |
| FLUIDS | | |
| Engine Oil/Filter Change | Passed | Ok |
| Coolant | Passed | Ok |
| Brake Fluid | Passed | Ok |
| Automatic Transaxle/Transmission Fluid | Passed | Ok |
| Transfer Case Fluid | Passed | Ok |
| Drive Axle Fluid | Passed | Ok |
| Power Steering Fluid | N/A | Electronic |
| Manual Transaxle/Transmission Hydraulic Clutch Fluid | N/A | Automatic Transmission |
| Washer Fluid | Passed | Ok |
| ENGINE | | |
| Fluid Leaks | Passed | Ok |
| Hoses, Lines and Fittings | Passed | Ok |
| Belts | Passed | Ok |
| Wiring | Passed | Ok |
| Oil in Air Cleaner Housing | Passed | Ok |
| Water, Sludge or Engine Coolant in Oil | Passed | Ok |
| Oil Pressure | Passed | Ok |
| Relative Cylinder Compression Test/Power Balance Readings (check if necessary) | N/A | Untested |
| Timing Belt | N/A | Untested |
| Engine Mounts | Passed | Ok |
| Inspect Turbocharger Air Cooler | N/A | |

| COOLING SYSTEM | | |
|---|--------|-----------------|
| Radiator | Passed | Ok |
| Pressure-Test Radiator Cap and Radiator | Passed | Ok |
| Cooling Fans, Clutches and Motors | Passed | Ok |
| Water Pump | Passed | Ok |
| Coolant Recovery Tank | Passed | Ok |
| Cabin Air Filter | Passed | Ok |
| FUEL SYSTEM | | |
| Fuel Pump Noise Normal | Passed | Ok |
| Fuel Pump Pressure | Passed | Ok |
| Fuel Filter | Passed | Ok |
| Engine Air Filter | Passed | Ok |
| ELECTRICAL SYSTEM | | |
| Starter Operation | Passed | Ok |
| Ignition System | Passed | Ok |
| Battery | Passed | 12.47 v |
| Alternator Output | Passed | 13.54 v |
| Diesel Glow Plug System | N/A | Gasoline Engine |
| UNDER CHASSIS | 35 | |
| PASSED | 29 | |
| REPAIR | 0 | |
| REPLACEMENT | 0 | |
| N/A | 6 | |
| FRAME | | |
| Frame Damage | Passed | Ok |
| Fuel Supply System | Passed | Ok |
| EXHAUST SYSTEM | | |
| Exhaust System Condition | N/A | |
| Emissions Control Test | N/A | |

| TDANGAROOLON | | |
|---|--------|------------------------|
| TRANSMISSION, TRANSAXLE, | | |
| DIFFERENTIAL AND | | |
| TRANSFER CASE | | |
| Automatic | Passed | Ok |
| Transmission/Transaxle | | |
| Manual Transmission/Transaxle , Differential and Transfer Case | N/A | Automatic Transmission |
| 4x4 Hub Operation | N/A | |
| Universal Joints, CV Joints and CV Joint Boots | Passed | Ok |
| Transmission Mounts (not cracked, broken or oil-soaked) | Passed | Ok |
| Differential/Drive Axle | Passed | Ok |
| TIRES AND WHEELS | | |
| Tires Match and Are Correct Size | Passed | 185/60R15 |
| Wheels Match and Are Correct Size | Passed | Ok |
| Tire Tread Depth – Front Tires (L/R) | Passed | 6mm |
| Tire Tread Depth – Rear Tires (L/R) | Passed | 6mm |
| Normal Tire Wear | Passed | Normal |
| Tire Pressure – Front Tires (L/R) | Passed | 30 psi |
| Tire Pressure – Rear Tires (L/R) | Passed | 32 psi |
| Tire Pressure Monitoring System | N/A | |
| No Evidence of Wheel Curb Damage | Passed | Ok |
| Wheel Covers and Center Caps | Passed | Ok |
| Rack-and-Pinion, Linkage and Boots | Passed | Ok |
| Control Arms, Bushings and Ball Joints | Passed | Ok |

| Tie Rods and Idler Arm | Passed | Ok |
|--|--------|-----------------------|
| Sway Bars, Links and Bushings | Passed | Ok |
| Springs | Passed | Ok |
| Struts and Shocks | Passed | Ok |
| Wheel Alignment (check if necessary) | Passed | Ok Based on Tire Wear |
| Power Steering Pump | N/A | Electronic |
| BRAKES | | |
| Calipers and Wheel Cylinders | Passed | Ok |
| Brake Pads and Shoes – Front Brakes (L/R) | Passed | Ok |
| Brake Pads and Shoes – Rear Brakes (L/R) | Passed | Ok |
| Rotors and Drums | Passed | Ok |
| Brake Lines, Hoses and Fittings | Passed | Ok |
| Parking Brake | Passed | Ok |
| Master Cylinder and Booster | Passed | Ok |